Certificate of Location of Government Corner

ID#: 841904 **Description:** 1/4 SEC COR 19 30 84 **Date Set:** 6/29/2004 **County:** Olmsted

Section: 19 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' east of centerline of N-S twp road and 23' north of fence east
Spike in Elm E 103'
County highway disk in Pine SW 82.44'
County Survey Disk in E side PP #49480 SSW 69.12'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick, Deputy Surveyor; On true line between sections 19-30. 38.22 chs set quarter section post. RPs- 12" aspen N46°E 100 links, 12" aspen S44°E 15 links.

5-1899 Robert Fraser Pg.642 No.578, County Surveyor, no evidence or knowledge of the corner. Dug over a large area and set no corner.

1913 David William, County Surveyor, (Pg.212 to 221 Bk.B) Did a lot of measuring, but doesn't call for any corner.

5-8-1975 County Surveyor set 1"x30" iron shaft at Gov't Proportionate Measure. RPs-spike in elm 103', spike & disc in pine 82.44' spike & CSD in 2" pine 46.11', Corner comes 23' north of fence east and 4' east of centerline.

12-4-2002 County Surveyor found 1" iron shaft down 0.2' in good condition.

6-29-2004 County Surveyor found 1" iron shaft down 0.2' in good condition. Took local ties and removed. Set 5' cast iron cap on telspar pipe down 0.3' at shaft location.