Certificate of Location of Government Corner

ID#: 841906 **Description:** W 1/4 SEC COR 19 84 **Date Set:** 8/4/2000 **County:** Olmsted

Section: 19 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3 1/2' north of centerline of CSAH 12 and 7 1/2' west of centerline of twp road south
Traverse point "60th Ave" S 79.87'
County highway disk in SE side new 8" cresoted CP NE 40.14'
County highway disk in W side PP #36776 N 44.82'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Ball, Deputy Surveyor North between sections 19 and 24. 40.00 chs. Set quarter section post. Br. Oak 10 in. N30°E 426 lks. Br. Oak 5 in. N5°W 884 lks.

4-1871 R. Perry (P. 181 No. 192), County Surveyor, states corner gone. Relocated corner from one bearing tree standing and one bearing tree stump. Set boulder and stake beside it.

1-1892 Thomas Fraser (P. 468 No. 450), County Surveyor, states corner gone. Set iron stake midway and on line.

1935 county highway department set iron midway and on line.

1942 John Kerr (B. 27 P. 13) ran and measured from N.W. 19 to S.W. 30. Set rod in road at 1/4 distance. Rpa- hub N 60.8, spike fence post N 33.0, hub fence line NE 67.4, hub in fence line SW 68.4, spikein fence post NE 42.8.

11-30-1973 County Surveyor dug to clay in area of corner but found nothing. Set C.I.M. over 5/8" x 13" rod midway and on line. RPs- 40.14 C.H. Disc in S.E. side new 8" cresoted corner post. Bit. Surface C.R. # 12. Twp. Road crushed rock. North 44.82' Co. Hwy. Dept. disc on W. side P.P. # 36776, Corner lies 3' N of CR# 12 centerline & 8'W of centerline of road south.

8-18-1999 County Surveyor found CIM down 0.1' in blacktop in good condition.

8-4-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

12-5-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

7-27-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.