Certificate of Location of Government Corner

ID#: 842004 **Description:** 1/4 SEC COR 20 29 84 **Date Set:** 11/1/2012 **County:** Olmsted

Section: 20 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface.
The corner falls 1' north of line of fence running east & 45' south of centerline of residential drive east.
Sign on cornerpost 15.5' East
This corner is located by GPS measurement

Corner History:

1854 Gov't notes, M.Karrick; 40.0 set temp 1/4 section post west on true line between sections 20 & 29. 40.0 set 1/4 section post in mound with trench, pits, charred stakes and osage orange seeds NE & SW.

8-1871 R. Perry by T. Hunter (Book A, Pg.188 No.199) Corner gone. Reset corner M & L

7-1912 C.Larson (Book B, Pg.196) Set stake M & L.

4-29-1913 D. Williams (Book B, Pg.213-221) Set iron stake M & L. Came 1' south of fence used to set center 20.

4-1960 J.Kerr Bk.78 Pg.75; Set 3/4" pipe. Pipe came 2.85' south of E-W fence.

8-1970 County Surveyor found pipe set by Kerr.

9-1977 Mn/Dot provided RPs to pipe. Show corner 3.5' south of E-W fence, CN&D in corner fence post up 1.5' on N side ENE 35.77', CN&D in brace post up 2.0' on south side ESE 37.49', CN&D in fence post up 2.0' on SW side SE 66.79'.

3-9-2001 Mn/DOT Survey Crew found monument in good condition.

4-2-2001 County Surveyor found 3/4" pipe down 0.7' in good condition.

9-20-2004 County Surveyor found 3/4" pipe down 0.5' in good condition. Took local ties and set a 7.0' telspar pipe w/CIC over pipe at surface.

9-27-2004 Mn/DOT Survey Crew found monument in good condition.

11-1-2012 County survey crew set 6' Telspar pipe with cast iron cap at previously measured GPS location after the existing monument was destroyed by construction.