Certificate of Location of Government Corner

ID#: 842005 **Description:** SEC COR 19 20 29 30 84 **Date Set:** 12/13/04 **County:** Olmsted

Section: 20 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.5'
The corner falls 1' west of centerline of N-S twp road and in line with fence east
County Survey Disk in CP E 34.92'
1/2" rod on N side of fence E 68.57'
Punch hole in S end 18" CMP NNW 111.13'
This corner is located by GPS measurement

Corner History:

7-1854 Gov't Notes: Michael Karrick, Deputy Surveyor North between sections 29 and 30. 80.00 chs. Set post for corner to sections 19-20-29-30. Erected mound with trench, pits, charred stake, and orange seeds at each angle.

8-1871 Thomas Hunter (P. 188 No. 199), County Surveyor, states corner gone, "sunk" boulder in line of old fence and in center of road fences.

5-1899 Robert Frasr (P. 642 No. 598), County Surveyor, could not find boulder and the fences were gone and the road had changed 4 or 5 times.

7-1912 Charles Larson (P. 196 Book B), County Surveyor, found boulder 8" x 14" x 20" midway and on line.

1913 Dave Williams (P. 219 Book B), County Surveyor, measured from 1/4 Cor. 17-18 South for 3 miles and set an iron rod midway and 5280' from S.E. Cor. Sec. 20 for the section corner.

8-1966 John Kerr, County Surveyor, did a lot of measuring and set a 120d nail in line of fence East.

5-4-1972 County Surveyor found 120d set in 1966. Dug and found nothing but large boulders and sand. Dug out West half of road.

5-8-1975 County Surveyor set CIM. RPs-34.94 Co. Surv. Disc in corner post. 68.57 1/2" rod on the N. side of fence. 32.7' Line of fence on W. side of road. 111.13' Punch hole in S. end 18" C.M.P.

3-7-2001 Mn/DOT Survey Crew found monument with head broken off.

4-2-2001 County Surveyor found CIM down 0.8' with head missing in good condition.

9-23-2004 Mn/DOT Survey Crew found monument with head missing.

12-13-2004 County Surveyor found CIM with head broken off down .8' in good condition. Pulled monument and set cast iron cap on telspar pipe as corner.

8-25-2011 County survey crew found cast iron cap in good condition