Certificate of Location of Government Corner

ID#: 842006 **Description:** 1/4 SEC COR 19 20 84 **Date Set:** 8/4/2000 **County:** Olmsted

Section: 20 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 12, 5 1/2' west of centerline of twp road north and 2' west of centerline of twp road south
Pk nail in wood post SW 65.24'
Hole in top of RCP SE 51.23'
5/8" iron pin NW 42.96'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor North between sections 19 and 20. 40.00 chs. Set quarter section post in mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W.

7-1912 Charles Larson (P. 196B), County Surveyor, set a stake midway and on line as the corner.

1913 Dave Williams (P. 219B), County Surveyor, set an iron stake midway and on line as the corner. RPs- tele pole NE 57.4', corner fence post NW 52.5', coast geo marker NE 67.92'.

1935 County Highway Department (B. 86 P. 78) found a 12" round concrete monument marked 1/4 corner. RPs- USGS B.M. NE 67.8, corner fence post SE 47.5', tele pole NW 68.7'.

1946 County Highway Department (B. 142 P. 2) records a 3/4" reinforceing rod at the corner.

5-31-1977 County Surveyor removed the 1" x 36" rod set 5-31-1977 and set a C.I.M. over a 5/8" x 12" rod at its location as the corner. RPs-Bench mark N.E. 67.96'. Punch hole in East end C.M.P. S.E. 35.60'. Punch hole in West end C.M.P. S.W. 34.35'. Centerline Co. Rd # 12. Plastic disc in top of corner post N.W. 53.62'. Note: The corner is in centerline of the E-W road and in centerline of crushed rock road South and 11' West of the centerline of road North.

9-30-1977 County Surveyor removed 1"x36" rod and set a CIM over a 5/8"x12" rod in new blacktop.

8-19-1999 County Surveyor found CIM in good condition down 0.2'. Set ref pipe and tied out corner.

8-4-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

4-2-2001 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-26-2003 Johnson & Scofield found aluminum cap flush with bituminous surface in good condition.

2-12-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

9-22-2004 Mn/DOT Survey Crew found monument in good condition.