Certificate of Location of Government Corner

ID#: 842009 **Description:** SEC CEN 20 84 **Date Set:** **County:** Olmsted

Section: 20 **Township:** 108N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

Reference Ties:

This corner is located by GPS reference stations "5508O A & B"

Corner History:

7-1912 Charles Larson (Book B P. 196) set an iron stake with lime under 3' deep for the center 20. He found a limestone in mound at the N. 1/4 Cor. 20 and set stakes midway at the E. 1/4 Cor. 20, the W. 1/4 Cor. 20, and the S. 1/4 Cor. 20.

1913 D. Williams (Book B P. 219) set a stake at intersecting 1/4 lines after finding the N. 1/4 Cor. 20 and setting the E. 1/4 Cor. 20, the W. 1/4 Cor. 20, and the S. 1/4 Cor 20 midway and on line.

4-21-1960 John Kerr (Kerr Book 78 P. 75), County Surveyor, shows a 1" pipe at the center 20 after he set the E. 1/4 Cor. 20 and the S. 1/4 Cor. 20 midway and on line and found a pipe at the W. 1/4 Cor. 20 and found a stone at the N. 1/4 Cor. 20.

6-1964 John Kerr (certificate filed) found a 1" x 3' pipe. Set a C.I.M. over a sash weight. RPs- hwy controll access sign SSW 10.0, disc pp SSE 37.2, corner lies in shallow pit in south ditch E-W.

4-21-1975 County Surveyor dug and found Larson's iron rod and lime 1.7 deep, .4 West and 1.7 South of Kerr's C.I.M.

3-31-1977 McGhie & Betts found and used CIM.

9-8-1977 Mn/Dot found Kerr's C.I.M. and took references. RPs- Corner 70' west of centerlince SBL T.H.52 and 24' south of centerline CSAH 12, CN & D up 1.0 on East side brace post 16.93.(gone) CSD in West side of tele post stub with box 76' SSE 34.44' (1985). 1964 Kerr RPs: Highway controlled access sign SSw 10.0 Disc in power pole SSE 37.2. CN & D in corner fence post up 1.0 on NW side 10.99(gone), CN & D up 1.0 on North side fence post(27.98) now 28.08, CSD west side telephone post stub with box SSE 34.44.

1-1979 County Surveyor has accepted Kerr's C.I.M. as the center of section 20.

6-1985 County Surveyor found CIM ok and took new reference point. RP- CSD west side tele pole stub with box SSE 34.44.

6-18-2001 County Surveyor set 120d spike down 0.3' from CSAH 12 construction control coordinates.

6-19-2001 County Surveyor set 6' telspar pipe w/CIC down 0.6' over 120d spike.

1-24-2002 V. Fangman found and used cast iron cap on telspar pipe

1-27-2003 Mn/DOT Survey Crew found monument in good condition.

9-22-2004 Mn/DOT Survey Crew found monument in good condition.

2-6-2006 County Surveyor found telspar w/CIC in good condition down 0.3'

8-1-2006 County Surveyor found corner destroyed by TH 52 construction.