Certificate of Location of Government Corner

ID#: 842104 **Description:** 1/4 SEC COR 21 28 84 **Date Set:** 6/24/81 **County:** Olmsted

Section: 21 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2 1/2' west of fence north and 1 1/2' south of E-W fence
Spike in CP NE 2.28'
Spike in brace post NW 5.16'
Sign on brace post 1 1/2' N
This corner is located by GPS reference stations "Shamrock A & B"

Corner History:

6-1854 Gov't Notes: Michael Karrick, Deputy Surveyor West on true line between sections 21 and 28. 40.00 chs. Set quarter section post in mound with trench, pits, charred stake, and Osage Orange seeds N.E. and S.W. 80.00 chs. Section Corner.

6-1867 H.E. Horton, County Surveyor, (Book A, Page 85, Surey No. 131) possibly used this corner to set the center 28.

3-1896 William Fraser, County Surveyor, (Book A, Page 592, Survey No. 538) "Found mound and pits all plain with post of fence in center of mound of fence running East and West over said corner. Drove stake marked 1/4S in center of mound by side of fence post." He used this corner to set a property corner 14.43 & 3/4 chains East and on line to the 1/16 East which he set midway (19.90 chs.) and on line to Sec. Cor. 21-22-27-28. He also "Found corner as located in survey on Page 85" at the center 28 and found it to be on line to 1/4 Cor. 28-33.

1969 McGhie and Betts set a 5/8" rod as the corner on line from Sec. Cor. 21-22-27-28 (set by Kerr) over old fence post at property corner set by Will Fraser 14.43 & 3/4 chs. East of 1/4 Cor. 21-28 and at Fraser's prorated measure. Corner came 2' South of the E-W fence and 5' West of fence running North. Dug here but found nothing.

4-1974 County Surveyor found Sec. Cor. 21-22-27-28 .8 North and 4.4 East of Kerr's corner (removed).

6-24-1981 County Surveyor dug for Will Fraser's stake and found appx. 4" of stake remaining plus 6" of mark down into clay. Set a Cast Iron Monument over a 5/8" rod at the stake location. This corner appx. 3.5 East and .5 North of McGhie and Betts iron (removed). rpS-Spike in corner post NE 2.28. 1Spike in brace post NW 5.16. Survey Marker Sign on brace.

3-16-2001 Mn/DOT Survey Crew found monument in good condition.

12-5-2002 County Surveyor found CIM at surface in good condition.