Certificate of Location of Government Corner

ID#: 842105 **Description:** SEC COR 20 21 28 29 84 **Date Set:** 6/22/01 **County:** Olmsted

Section: 21 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of fence east and 1' east of fence north
County Survey Disk (up 1') in 12" tree NE 28.09'
County highway disk up 0.5' in W side fence post NNW 11.05'
Post w/sign 1 1/2' north
This corner is located by GPS reference stations "Larsen A & B"

Corner History:

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor North between sections 28 and 29. 80.00 chs. Set post for corner to sections 20-21-28-29. Erected mound with trench, pits, charred stake and Osage Orange seeds at each angle.

8-1871 Robert Perry (Book A P. 188 No. 199 by Hunter) found old stake in mound with impression fo pits all right. Used the corner to set 1/4 Cor. 20-29 midway (39.88 chs.) and on line.

7-1912 C. Larson (Book B P. 196) found a limestone and used it to set 1/4 Cor. 20-29 (shows it midway 39.88 chs.).

1913 D. Williams (Book B P. 215) states: "found the remains of an old stake. Sometime in June 1912 while making a survey of these lines for the Oronoco Town Board. Mr. Ihrke, the Chairman showed me this corner and said it was correct. At that time there was a boulder stone there and I did not disturb it. When I looked for this corner in this Survey the stone was gone but the impression of it remained plain. Upon digging further into this hole I found the stake." He shows a boulder with a cross on top.

4-1960 John Kerr Bk.78 Pg.75 (certificate filed), County Surveyor, found a boulder stone. Set 3/4" pipe.

6-1964 J. Kerr set CIM over 3/4"x12" rod & limestones. RPs- corner lies 2.5' SE of corner post, 3/8"x4' rod up 2' south .5'.

4-21-1975 County Surveyor dug farther North and West from Kerr's C.I.M. Did not find anything else except old post stub 3' N.W.

9-21-1977 Mn/Dot found the C.I.M. and took reference points. RPs-CN & D in 4" Choke cherry (up 2.0' on North side) 28.06. R/W post up 3'. C.I.M. 3/8" x 4' rod up 2.0' South .45. Corner 2' South of E-W fence and 1' East of N-S fence. CN & D up 0.5' on West side of corner fence post 2.05'. CN & D up 0.5' on West side of fence post 11.02'.

3-9-2001 Mn/DOT Survey Crew found CIM leaning west.

4-2-2001 County Surveyor found CIM up 0.4' leaning west.

6-22-2001 County Surveyor found CIM up 0.4' leaning West. Removed CIM and dug down to 3/4" rerod and limestone. Removed rerod and stone and set 4' long telspar w/CIC at stone postion at surface.

9-27-2004 Mn/DOT Survey Crew found monument in good condition.