Certificate of Location of Government Corner

ID#: 842204 **Description:** 1/4 SEC COR 22 27 84 **Date Set:** 11/3/2006 **County:** Olmsted

Section: 22 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' east of centerline of CR 112 and 13' south of centerline of Sattre Dr. NW
County Survey Disk in S side PP #2443 NE 54.51'
County Survey Disk in N side PP #43209 WNW 48.73'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: M.G. Karrick, Deputy Surveyor West between sections 22 and 27. 40.00 chs. Set quarter section post. Made mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W. 80.00 chs. Section corner.

6-1884 Thomas Hunter (P. 390 No. 381), County Surveyor, found stake in center of road set in Survey of 1881 (unrecorded) when stake was found in mound.

11-1894 William Fraser (P. 555 No. 512), County Surveyor, found Hunter's stake. Made a pile of stones around stake with stone on top of stake.

3-1896 William Fraser (P. 592 No. 538) found corner of P. 555.

2-1941 John Kerr (B. 23), County Surveyor, found stake and rocks. Set 1" pipe with 1/2" pipe inside.

4-1967 John Kerr found corner 3' deep. Set C.I.M. over a short 1/2" rod driven into original pipe by stone. RPs- 30D nail & rag N side pp WNW 35.45(gone), 30D nail & rag SE side ppNE 43.94(gone), bottle cap N side tele pole ESE 49.7(gone).

1968 Co.H.D. (B. 326) found C.I.M.

8-22-1969 John Kerr pulled C.I.M. set 1/2" rod flush and referenced. RP- 1/2" rod east 100' on AZ line of black tele pole east of bldgs.

6-12-1974 County Surveyor found rod and proved with 1969 reference points. Reset a C.I.M. over a 1/4" x 8" rod. RPs- CSD disc south side pp NE 54.44, county highway department disc North side pp WNW 52.34, county highway department disc south side tele pole SE 49.61.

10-11-2005 County Surveyor found CIM in good condition down 0.6', took local ties and removed.

10-15-2005 County Surveyor set 1" square pipe w/cap at surface from CIM ties. CSD with concrete nail in north side of PP #43209, CSD on SE side of PP #24413 NE 54.50'.

2-7-2006 County Surveyor found 1" square pipe w/cap in good condition at surface. Set reference pt and tied out corner for 2006 overlays.

7-21-2006 County Surveyor removed 1" square pipe w/cap for overlay.

11-3-2006 County Surveyor set 1" square pipe w/cap at surface from reference angle, updated ties.