Certificate of Location of Government Corner

ID#: 842304 **Description:** 1/4 SEC COR 23 26 84 **Date Set:** 8/17/2005 **County:** Olmsted

Section: 23 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in N side Oak W 42.74'
County Survey Disk in E side Elm S 15.61'
County Survey Disk in N side twin Oak E 26.10'
Post w/sign 2' west
This corner is located by GPS reference stations "McClure E & F"

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set temp 1/4 section post west on true line between sections 23&26. 40.0 set 1/4 section post. RPs- 12" burr oak N40 E245, 10" burr oak S49 E245.

6-1881 T. Hunter Pg.123 No.371, unrecorded survey. Subdivided section 26. Set N 1/4 26.

5-1902 W.Fraser Pg.18B; found hunter's records, plat in book copy of original Hunter survey, found center 26, E & S 1/4 corners & SE corner. Didn't go to or use 23-36. In river lands, rough wooded etc., river likely west of 1/4 23-26.

1916 Power Dam Survey used N-S fence as corner.

8-27-1941 J. Kerr Bk. 25 pg. 70 measured the E-W line between sections 23 and 26.

4-17-1974 County Surveyor set a 3/4"x3' rod 3.4' SW of old corner post. Set the corner midway and on line by electronic traverse. RPs- spike & CSD disc in 16" oak SSE 42.25', spike & CSD disc in 18" oak E 55.37', spike & CSD disc in 10" twin oaks NE 26.12'.

8-17-2005 County Surveyor found 3/4" rod up 0.6' in good condition. Took local ties drove rod down and set 4' cast iron cap on telspar pipe up 0.4' over rod.

10-31-2005 County Surveyor found telspar pipe w/CIC in good condition up 0.4'.