Certificate of Location of Government Corner

ID#: 842805 **Description:** SEC COR 28 29 32 33 84 **Date Set:** 7/12/2006 **County:** Olmsted

Section: 28 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' south of centerline of CR 154 and 34 1/2' east of center of manhole
This corner is located by GPS measurement and by GPS reference stations "PWT B & C"

Corner History:

7-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor North between sections 32 and 33. 80.00 chs. Set post for corner to sections 28-29-32-33. Erected mound with trench, pits, charred stake, and Osage Orange seeds at each angle.

5-1873 Thomas Hunter (P. 224 No. 227), County Surveyor, found the stub of the old stake in the center of the road avered by a Mr. A. Hannon and others to be where the original corner stood. Set two stones 2" x 6" x 15" side by side.

11-1912 Dave Williams (P. 186B), County Surveyor, found two limestones side by side with the stake between on the South side of the center of the road.

8-1964 John Kerr, County Surveyor, set a C.I.M. over a 5/8" x 2' pipe as the corner at the location of the corner in place.

4-26-1972 County Surveyor dug with the backhoe and found the 2" x 6" x 15" limestones with an old stake between them as recorded by Hunter 2.0' West and .3' South of Kerr's C.I.M. (removed). Set a 3/4" x 2' thin wall conduit between the stones and in the old stake remains.

9-29-1977 County Surveyor found a rod possibly set by the County Highway Department removed the rod and set a C.I.M. over a 5/8" x 14" rod as the corner from references taken in 1972.

6-4-1998 County Surveyor found CIM in good condition. Referenced corner before cold recycling bituminous surface of C.R. #154. Set ref. Pipe/cap NW of corner near Peoples Coop Oronoco substation.

10-20-1998 County Surveyor set P.K. Nail in new bituminous surface from 6-4-1998 reference.

6-10-1999 County Surveyor set 1" square pipe w/cap at surface.

4-2-2001 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-25-2003 County Surveyor found 1" square pipe w/cap at surface in good condition. Set points and tied out corner for Hwy 52 construction.

9-23-2004 Mn/DOT Survey Crew found monument in good condition.

1-24-2006 County Surveyor found corner destroyed due to construction.

7-12-2006 County Surveyor set 1" square pipe w/cap from computed coordinates at surface