Certificate of Location of Government Corner

ID#: 843004 **Description:** 1/4 SEC COR 30 31 84 **Date Set:** 5/12/75 **County:** Olmsted

Section: 30 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 4' south of centerline of E-W twp road and 21' west of centerline of driveway south
County Survey Disk in mailbox SW 24.0'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: W.B. Yerby, Deputy Surveyor East on true line between sections 30 and 31. 39.60 chs. Set quarter section post in mound of earth and sod. Deposited charcoal. Made trench and pits and planted Osage Orange seed North and South.

5-1870 Robert Perry (P. 112 No. 149), County Surveyor, found stone avered by old settlers as the true corner.

5-1899 Robert Fraser (P. 642 No. 578), County Surveyor, found boulder stone 10" x 14" x 18" with point upward in line with fences North and South.

8-1966 John Kerr, County Surveyor, measured the North line of Section 31 and set a 5' rod to hold point. Dug but found nothing. RP- 34' SE to corner post east lane fence South.

5-8-1972 County Surveyor dug and found the recorded stone 3.5' deep and set a 1" x 3' pipe over the stone to hold location as the road was being graded. RPs- 60' south of cross in bridge wall 21.7 S of stone found, placed old tv picture tube broken and ols scoop shovel blade by stone and much glass & cans.

4-1973 County Surveyor found 1 1/4" pipe. Road to be graded. Set transit on pipe shot to center pp on road 1/2 mile west, 1st pole N of W 30-31 300'±. Set 3/4"x8" rod 1' south of north edge road west 100' which comes 24.88 due south of 60D east side 6" cedar tree.

12-1973 Cedar tree done. Road graded it corner, all changed, rod on north edge road 100' WNWly may be there.

5-12-1975 County Surveyor dug down and found our pipe slightly bent. Dug down to stone and set a C.I.M. over a rod over the stone. The corner falls 4' South centerline of the East-West road and 21' West of the centerline of the driveway South. RPs-24.0' Co. Surv. Disc in mailbox. 3/4" x 8" rod 1' South of N. edge of road 100'.

12-3-2002 County Surveyor found CIM down 0.2' in good condition.