Certificate of Location of Government Corner

ID#: 843104 **Description:** S 1/4 SEC COR 31 84 **Date Set:** 5/25/1999 **County:** Olmsted

Section: 31 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 4' north of centerline of CSAH 14, in line with fence north and 113' east of centerline of field drive north
County Survey Disk in W side CP N 59.65'
County Survey Disk in PP #24095 SE 79.50'
Ref pipe NW 132.44'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor, West between sections 6 and 31. 40.00 chs. Set post and drove charred stake for quarter section corner. Built mound with trench and planted Osage orange S.E. and apple seed N.E. 77.80 chs. Section corner.

5-1870 Robert Perry (P. 112 No. 149), County Surveyor, found a stone as the corner avered by the oldest settlers as to its correctness as the true corner.

6-1874 Thomas Hunter (P. 229 No. 232), County Surveyor, found a stone boulder avered set by a Mr. Gere when and where the original corner stood.

7-1917 John Kerr (P. 270B), Deputy County Surveyor, found a stone in the bottom of the road fill and in line with the N-S fences and 33' from both fences.

6-8-1977 The County Surveyor dug with the backhoe and found a 10"x11"x18" boulder with a stake on the West side. Set a 1/2"x2' rod over the stone at the road surface. RPs- Corner in line with fence north, CSD in pp# 24095 SE 79.50, CSD in W side corner post N59.65.

11-8-1977 The County Surveyor set a C.I.M. over a 1/2"x12" rod in place of the 1/2" rod set 6-8-1977. RPs- Corner 4' N of centerline & in line with fence north.

5-13-1998 County Surveyor found CIM in good condition 3.7' North of centerline C.R. #14. Referenced corner before cold recyling bituminous surface of C.R. #14. Set ref. Pipe 14' west of centerline field drive North side CR# 14.

8-18-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-13-1998 referenced.

5-25-1999 County Surveyor set 1" square pipe w/cap at surface.

2-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.