Certificate of Location of Government Corner

ID#: 843105 **Description:** SW SEC COR 31 84 **Date Set:** 6/7/1999 **County:** Olmsted

Section: 31 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' south of centerline of CSAH 14 and in centerline of N-S twp road
Punch mark in top lug on W end CMP NW 35.96'
Punch mark in top lug on E end CMP NE 37.39'
Punch mark in top lug on W end CMP SW 35.57'
Punch mark in top lug on E end CMP SE 38.00'
3/4" iron (5 1/2' NNW of 21" Pine) SW 96.52'
County Survey Disk in PP SW 58.50'
County Survey Disk in PP #48952 SE 58.33'
Ref pipe NNE 81.08'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor, North between sections 1 and 6. 80.00 chs. Set post and drove charred stake for corner. Built mound with trench and planted Osage Orange S.E. and apple seed N.E.

1875 State law required that township monuments be placed at the township corners. Thomas Hunter, County Surveyor, placed stone monuments as required although there is no survey notes documenting this particular corner

4-1919 Charles Armstrong (P. 302B), County Surveyor, found an engraved monument as the corner.

1931 County Highway Department (B. 63 P. 3) found a large boulder .3' above the surface.

1961 County Highway Department (B. 234 P. 3) records a 7/8" rod over a 8"x8"x30" concrete monument as the corner. RPs- disc inf ence post SE 88.44, reinforcing rod by pine tree SW 96.48, 3/4" pipe NW 46.5, center 18" spruce SW 101.7.

6-2-1977 County Surveyor dug with the backhoe and found an 8"x8"x24" concrete monument over the remaining 24" of the 10"x10" cut stone township monument. Set a 3/4"x2' pipe on the south side of the stone and reset the concrete monument over the stone. Set a 1/2"x15" pipe over all at the road surface. RPs- corner 1 1/2' south of centerline CR# 14 and 1 1/2' W centerline road north and south, Punch mark in top lug on west end C.M.P. N.W. 35.96', Punch mark in top lug on east end of C.M.P. N.E. 37.39',
Punch mark in top lug west end of C.M.P. S.W. 35.57', Punch mark in top lug on east end C.M.P. S.E. 38.00', 3/4" iron 51/2' N.N.W. of a 21" pine S.W. 96.52'.

11-8-1977 County Surveyor replaced the 1/2" pipe set 6-2-1977 with a C.I.M.

5-13-1998 County Surveyor found CIM in good condition 1 1/3' South of centerline C.R. #14. Referenced corner before cold recycling bituminous surface of C.R. #14. Reference pipe 30 1/2' east of centerline 60th Ave & 73.6 north of CR# 14.

9-21-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-13-1998 referenced.

6-7-1999 County Surveyor set 1" square pipe w/cap

2-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-17-2004 County Surveyor found 1" square pipe w/broken cap at surface in good condition. Replaced cap.