Certificate of Location of Government Corner

ID#: 843204 **Description:** S 1/4 SEC COR 32 84 **Date Set:** 5/25/1999 **County:** Olmsted

Section: 32 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' south of centerline of CSAH 14 and in line with fence south
Punch mark in lug on W end CMP NE 39.98'
County Survey Disk in N side PP #39577 SW 97.89'
Punch mark in lug on W end CMP SE 43.13'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor, West between sections 5 and 32. 40.00 chs. Set post and drove charred stake for quarter section corner. Built mound with trench and planted Osage orange S.E. and apple seed N.W.

5-1874 Thomas Hunter (P. 249 No. 250), County Surveyor, states that the corner was plowed out in the building of the road. A Mr. M. Beneke avers his fence south was 1 foot East of due south on his own land and started 2 rods from the corner when it was standing. Set a 8"x9"x22" boulder sunk well down as the corner at the location avered by Mr. Beneke.

7-1917 John Kerr (P. 270B), Deputy County Surveyor, found the stone P. 249.

6-7-1977 County Surveyor dug with the backhoe and found Hunter's boulder 5' deep. Set a 11/4"x15" pipe on the East side and 1/2"x12" rod on the West side of the boulder. Set a 1/2" rod at the surface of the road. RPs- CSD in N side pp# 39577 SW 97.89, punch mark in lug at top W end CMP in driveway S SE 43.13, punch mark in lug at top west end CMP in driveway N NE 39.98.

11-8-1977 County Surveyor replaced the 1/2" rod set 6-7-1977 with a C.I.M.

5-13-1998 County Surveyor found CIM in good condition, referenced corner before cold recycling bituminous surface of CR #14. Set reference pipe 52 1/2' south of CIM.

8-18-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-13-1998 reference.

5-25-1999 County Surveyor set 1" square pipe w/cap at surface of road.

3-7-2001 Mn/DOT Survey Crew found monument in good condition.

2-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

9-23-2002 Mn/DOT Survey Crew found monument in good condition.