Certificate of Location of Government Corner

ID#: 843205 **Description:** S SEC COR 31 32 84 **Date Set:** 5/25/1999 **County:** Olmsted

Section: 32 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' north of centerline of CSAH 14 and 5 1/2' west of centerline of twp road north
Punch mark in lug on W end CMP NW 32.62'
Punch mark in lug on E end CMP NE 38.85'
Ref pipe N 61.90'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor, West between sections 5 and 32. 80.00 chs. Set post and drove charred stake. Built mound with trench and planted osage orange S.E. and apple seed N.E.

6-14-1874 Thomas Hunter (Book A, P. 229 No. 232), County Surveyor, states that the corner was gone and there was no evidence or knowledge of it. Set a 4"x7"x18" stone as the corner by double proportionate measure from S. 1/4 Cor. 31 to S.1/4 Cor. 32 and from 1/4 Cor. 5-6 (T107N, R14W) to 1/4 Cor. 31-32 (T108N, R14W). When measuring from 1/4 Cor. 5-6 to 1/4 Cor. 31-32, Hunter found his total to agree with the sum of the Gov't. measures from 1/4 Cor. 5-6 to N. Sec. Cor. 5-6 in T107N and from S. Sec. Cor. 31-32 to 1/4 Cor. 31-32 in T108N, which apparently influenced him to prorate across the town line.

6-27-1917 John Kerr (Book B, P. 270), Deputy County Surveyor, could not find Hunter's corner. Set a stone as the corner midway and on line between the S. 1/4 Cor. 31 and the S. 1/4 Cor. 32.

6-8-1977 County Surveyor found that the corner comes in a deep cut in C.R. 14. Set a 5/8"x11" bolt as the corner midway and on line between the S. 1/4 Cor. 31 and the S. 1/4 Cor. 32.

11-8-1977 County Surveyor set a C.I.M. over the bolt set 6-8-1977. RPs-The corner falls 1-1/2' North of the centerline of C.R. #14 and 7' West of centerline of 50th Ave NW, corner falls 1-1/2' North of the centerline of C.R. #14 and 7' West of centerline of 50th Ave NW.

5-13-1998 County Surveyor found CIM in good condition. Referenced before cold recycling bituminous surface of C.R. #14. Set reference pipe 17' west of centerline 50th Ave & 62 1/2' north of centerline CR# 14.

8-18-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-13-1998 reference.

5-25-1999 County Surveyor set 1" square pipe w/cap at surface over found PK Nail

3-7-2001 Mn/DOT Survey Crew found monument in good condition.

9-4-2001 Mn/DOT Survey Crew found monument in good condition.

2-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.