Certificate of Location of Government Corner

ID#: 843304 **Description:** S 1/4 SEC COR 33 84 **Date Set:** 5/26/2005 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 14W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The monument is at the surface
The corner falls 2' south of centerline of CSAH 14 and 10' east of centerline of twp road north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor, West between sections 4 and 33. 40.00 chs. Set post and drove charred stake for quarter section corner. Built mound with trench and planted osage orange S.E. and apple seed N.E.

7-1902 Robert Fraser (Field Book 10, P. 52-53) could not find the corner. Set a temporary stake at the S. 1/4 Cor. 33 and at the S. Sec. Cor. 33-34 on the line from S.W. Cor. 33 to the S.E. Cor. 34 (a stone found) and at 1/4 and 1/2 the distance respectively. He shows the S. 1/4 Cor. 34 on this line and at 1/4 the distance also but does not say he set anything there.

11-1912 Dave Williams (P. 186B), County Surveyor, measured from the N. 1/4 Cor. 33 South to the center of the E-W road at the S. 1/4 Cor. 33.

10-1913 Dave Williams (P. 240B) set the S. 1/4 Cor. 33 and the S. 1/4 Cor. 34 on the line from the S.W. Cor. 33 to the S.E. Cor. 34 and at prorated Gov't measure (1/4 the distance). At the S.1/4 Cor. 33 he set a 4"x7"x13" light colored boulder as the corner which came in line with the fences North and South. At the S. 1/4 Cor. 34 he drilled a hole 1"x12" deep in a limestone ledge. He drove a wood plug in the hole and put broken coal around it with a tin sheet over it and stone slaps with one pointed up over the tin.

1916 John Kerr (P. 252B) found stones at S. 1/4 Cor. 33 and the S. 1/4 Cor. 34. Set a stone midway and on line between these 1/4 corners as S. Sec. Cor. 33-34.

1938 County Highway Department (P. 95) shows a stone at the corner.

1965 County Highway Department (B. 310) records a pipe in the black top. RPs- disc in fence post NE 39.42, disc tele pole SSE 30.24, spike top of fence post S 33.43.

1972 County Surveyor measured North to the N. 1/4 Cor. 33.

11-7-1977 County Surveyor dug with the backhoe midway and on line between the section corners. Found a nail in the blacktop to be set over a 1/2" rod .58 North and 1.08 West of the midway and on line location. Dug deeper and found a pipe over a stake over a 4"x9"x13" boulder (knocked over) .07 South and .43 West of the midway and on line location. Set the pipe on the East side of the stone and a 1/2" rod on the south side. Set a 3/8" rod at the road surface.

11-17-1977 County Surveyor set a C.I.M. over a 1/2"x20" rod as the corner midway and on line (removed the 3/8" rod set 11-17-1977). RPs- CSD in west side pp NNW 51.55, old disc in top of corner post S 34.06.

1991 county highway department took reference to corner. Set 1" sq pipe/cap on line to pp ± 325' south of corner at 85.82' before construction o fCR# 14.

6-11-1993 County Surveyor set 1" sq pipe/cap as corner. Corner falls in centerline CR# 14 in line of fence South & 1'East of line of poles north.

9-23-2002 Mn/DOT Survey Crew found monument in good condition.

6-23-2003 County Surveyor found corner gone due to Hwy 52 construction.

7-14-2003 County Surveyor set 60d spike at surface from 1992 CSAH 14 construction tie-out. Set 2 pts to the tie-out corner for Hwy 52 construction.

5-26-2005 County Surveyor set 5/8" copper plug w/punch mark at surface from 2003 tie out.

8-25-2011 County survey crew found 5/8" copper plug with punch mark in good condition.