Certificate of Location of Government Corner

ID#: 843309 **Description:** SEC CEN 33 84 **Date Set:** 2/28/2006 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 5 1/2' east of centerline of N-S twp road and 8' north of fence east
This corner is located by GPS reference stations "New Road A & B"

Corner History:

6-3-1867 H.E.Horton Pg.85 No.131; Corner used. Set 1/16 north.

7-1902 R.Fraser Bk.10 Pg.52; At I drove oak stake. Stake came in line with fence N & S.

11-1912 D.Williams Pg.186B; Found stone boulder.

10-24-1967 J.Kerr Bk.96 Pg.63-66; Reset corner with 1" pipe. Iron fell 8.7' north of fence running east and east of fence 2.0±

4-6-1990 County Surveyor found J.Kerr pipe N & E of fence intersection as called for on card.

5-10-1991 V. Fangman found and used pipe.

3-15-2001 V. Fangman found and used pipe.

3-19-2001 Mn/DOT Survey Crew found pipe in good condition. This work was done in the preparation of MNDOT Right of Way Plats No. 55-64 and 55-66. Both of these plats show a 1" pipe at the center of section.

1-21-2003 County Surveyor found 1" pipe in good condition up 0.2'. Monument falls near large stone. Monument to be destroyed by Mn/DOT road construction for T.H. 52.

2-17-2003 V. Fangman found and used pipe.

2-28-2006 County Surveyor set 1" square pipe w/cap at surface from angle turned before construction.

5-16-2006 County Surveyor found 1" square pipe with part of cap shaved off. Drilled out remaining cap and set new cap at surface.

3-6-2008 McGhie & Betts used computed center for survey in SE quarter section 33 breakdown.