8435Certificate of Location of Government Corner

ID#: 843405 **Description:** S SEC COR 33 34 84 **Date Set:** 6/14/1993 **County:** Olmsted

Section: 34 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of Trunk Highway 63, 10' east of tree line/fence row north and 79' west of centerline of driveway south
The monument is at the surface
Reference pipe NNW 77.11'
This corner is located by GPS measurement

Corner History:

10-5-1853 John Ball, Deputy Surveyor, measured west 80.00 chains on true line between Sections 3 and 34. Set post and deposit a handfull of small rock to Section Corner 3, 4, 33 and 34. Built mound with trench per instructions. Planted Osage Orange seed SE and Apple seed NE.

6-22-1854 Michael G. Karrick, Deputy Surveyor, measured north 79.50 chains on random line, between Sections 3 and 4, for subdivision of Cascade Township. Intersected north boundary 18 links (11.88') west of post.

6-27-1854 Michael G. Karrick, Deputy Surveyor, measured north from post, between Sections 33 and 34, for subdivision of Oronoco Township.

5-25-1858 Thomas Hunter, County Surveyor, (Old Road Book, Road No. 16, Page 122), used corner for road survey along the north line of Section 3.

7-2-1902 Robert Fraser, County Surveyor, (Old Field Book No. 10, Pages 52-53), set temporary stake.

10-18-1913 David Williams, County Surveyor, (Book B, Pages 240-241), found no corner. Used point on town line midway and on line between SE Corner 34 and SW Corner 33.

11-9-1916 David Williams, County Surveyor, per John Kerr, Deputy County Surveyor, (Book B, Pages 252-259), corner gone. Set stone midway and on line from North 1/4 Section 3 to North 1/4 Section 4. RPs - NE corner of north headwall N89°50'W 113.4', Drill Hole in rock face N46°15'W 86.7'.

4-17-1923 John Kerr, County Surveyor, (Kerr Field Book No. -8, Page 2), measured 5185.5' north on randon line between Sections 3 and 4. Intersected north boundary 18.1' west of corner. Does not mention type of monument.

8-10-1938 County Highway Department, (CHD Book No. 95, Page 5), used corner. Does not mention type of monument. P.O.T. Sta. 45+74.0. RPs - Drill hole in rock NW 85.63', Spike in boxelder (up 10') SW 55.9'.

1-14-1949 John Kerr, County Surveyor, (Kerr Field Book No. 40, Page 59), found monument. RPs - Drill hole in rock NW 85.63', Spike in boxelder (up 10') SW 55.9', Spike in boxelder SW 56.5'.

1950 Dug for corner and found stone down 4'. Set pipe over stone.

11-10-1965 County Highway Department, (CHD Book No. 310, Pages 1-2), found 1" pipe down 1'. P.I. Sta. 476+91.46. RPs - Spike & Disc in power pole NW 47.75', Spike & Disc in telephone pole SE 35.88', 2"x2" hub Nail & Disc under fence NE 53.75'.

9-27-1966 John Kerr, County Surveyor, found iron pipe over stone. Set Cast Iron Monument over 1" pipe packed in stones. RPs - Lead Slug in drill hole in limesteon ledge NW 85.65', Nail & Disc in telephone pole SE 35.9', Nail & Disc in power pole NW 47.68', 2"x2" hub Nail & Disc under fence NE 53.75'.

11-7-1977 County Survey Crew found Cast Iron Monument.

5-4-1979 County Survey Crew found Cast Iron Monument.

3-27-1988 County Highway Department, (CHD Book No. 310 A, Page 3), found Cast Iron Monument. P.I. Sta. 476+91.64. Set 1" square pipe w/cap as grading tie NNW 77.11' and referenced corner. RPs - Spike & Disc in top of corner post SE 75.3', Spike & Disc in corner post NNW 50.8'.

6-14-1993 County Survey Crew set 1" square pipe/cap as corner from 1988 construction grading tie. The corner falls in centerline of CSAH 14, 3' east of line of old bulkhead north, and 77-1/2' west of centerline of driveway south.

3-6-2001 Mn/DOT Survey Crew found monument in good condition.

8-8-2002 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.