Certificate of Location of Government Corner

ID#: 843505 **Description:** S SEC COR 34 35 84 **Date Set:** 6/11/1993 **County:** Olmsted

Section: 35 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of Trunk Highway 63 and 6' west of centerline of township road (11th Ave NW) north
The monument is at the surface
County Survey Disc in PP #50400 NE 86.71'
County Survey Disc in PP #52552 SE 60.99'
This corner is located by GPS measurement

Corner History:

10-5-1853 John Ball, Deputy Surveyor, measured west 80.00 chains on true line between Sections 2 and 35. Set post and drove charred stake to Section Corner 2, 3, 34 and 35. Built mound with trench per instructions. Planted.

6-21-1854 Michael G. Karrick, Deputy Surveyor, measured north 79.30 chains on random line, between Sections 2 and 3, for subdivision of Cascade Township. Intersected north boundary at post.

6-26-1854 Michael G. Karrick, Deputy Surveyor, measured north from post, between Sections 34 and 35, for subdivision of Oronoco Township.

10-20-1857 E.P. Bircher, County Surveyor, per John B. Fellows, Deputy County Surveyor, (Old Road Book, Road No. 53, Page 97), surveyed a road between Sections 34 and 35, T108N, R14W to post then west.

5-25-1858 Thomas Hunter, County Surveyor, (Old Road Book, Road No. 16, Page 122), surveyed a road on the north side of Section 3 from post.

2-8-1889 Thomas Hunter, County Surveyor, (Book A, Page 427, Survey No. 415), found stone. The corner falls on south side of track and in line with fence south.

1-3-1900 Robert Fraser, Deputy County Surveyor, (Book A, Pages 646-652, Survey No. 582), found stone and stake. Set boulder stones on top. The corner falls in south track of road, in line with fence south and centerline of road north.

10-18-1913 David Williams, County Surveyor, (Book B, Pages 240-241), found 6"x6"x12" boulder stone with rounding peaked top.

1916 Power Dam Survey found stone.

8-13-1938 County Highway Department, (CHD Book No. 95, Page 6), found stone. P.I. Sta. 98+48.1. RPs - Spike in telephone pole NE 67.04', Spike in cedar NW 55.15', Spike in Box Elder SW 70.6', Spike in Box Elder SW 33.75'.

8-1-1960 John Kerr, County Surveyor, (Book C, Page 70 and Kerr Field Book No. 80, Page 45), 1/2" rod. RPs - Spike in power pole NW 37.3', Spike in cedar NW 55.15', Spike in guy pole SSW 31.0', Spike in Box Elder SW 70.6'.

8-19-1965 County Highway Department, (CHD Book No. 310, Pages 1 & 3), found 3/4" iron rod. P.O.T. Sta. 529+66.09. RPs - Spike & Disc in telephone pole NE 67.04', Spike & Disc in power pole NNW 37.31', Spike & Disc in brace pole SSW 30.99'.

12-3-1965 John Kerr, County Surveyor, (Kerr Field Book No. 92, Page 25), used corner.

4-24-1979 County Survey Crew found 1/2" rod.

6-13-1980 County Survey Crew found 1/2" rod and removed. Dug and found 6"x8"x18" limestone down 4'. The stone falls 0.14' west and 0.07' north of 1/2" rod. Set 1/2" pipe over stone.

3-27-1988 County Highway Department, (CHD Book No. 310 A, Page 5), found 5/8" rod. P.I. Sta. 529+65.81. Set rod w/cap as grading tie NNW 249.06' and referenced corner. RPs - Spike & Disc in power pole NW 37.1', Spike & Disc in corner post NE 74.0', Spike & Disc in top of corner post S 34.0'.

5-30-1990 County Survey Crew found 5/8" rod and used for City of Rochester mapping project.

6-11-1993 County Survey Crew set 1" square pipe/cap as corner from 1988 construction grading tie. The corner falls in centerline of CSAH 14 and 6' west of centerline of 11th Ave NW. RPs - County Survey Disc in power pole #50400 NE 86.71', County Survey Disc in power pole #52552 SE 60.99'.

1-15-2003 County Survey Crew found 1" square pipe w/cap at surface in good condition with pk nail in the cap. Removed old cap and set new cap and measured its position using GPS.