# Certificate of Location of Government Corner

**ID#:** 843604 **Description:** S 1/4 SEC COR 36 84 **Date Set:** 6/14/1993 **County:** Olmsted

**Section:** 36 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls 3' south of centerline of CSAH 14
Reference irons S 84.08' and 128.75'
This corner is located by GPS measurement

**Corner History:**

4-1875 T. Hunter Pg.270 No.268; Corner gone. Reset corner from SE B.T. and stump NE BT.

8-1938 county highway department Bk.95 Pg.2; Set hub at N1/4 1. RPs- 8" oak SE 70.7, 8" oak NE 82.25.

3-1959 McGhie & Betts data; Set 5/8" rod in blacktop. RPs- spike S side pp ESE 102.25, spike W side 12" oak SE 70.5, spike W side 8" oak S 68.2, spike W side 8" ash NW 78.3, steel bridge E 227.0, center line road N 3.65'.

11-14-1962 J. Kerr found 5/8" iron rod.

1965 J. Kerr, RPs- drag tooth in road. RPs- hub N 39.92, spike in pp ESE 102.17, 3.78 south of center line.

4-19-1979 County Surveyor set reference rods before road const. Set 1/2"x25" rod S 84.08(5 1/2' E of a blazed 9" burr oak) on line to a 1/2"x26" rod 128.75 S of the corner(4 1/2' west of a blazed 8" elm).

6-14-1993 County Surveyor set 1" sq pipe/cap as corner. The corner falls 3' South of centerline CR # 14.

5-27-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.