Certificate of Location of Government Corner

ID#: 850106 **Description:** 1/4 SEC COR 1 2 85 **Date Set:** 10/26/77 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls NE'ly of TH 52 in open field area
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: Cushing, Deputy Surveyor; North on true line between sections 1 & 2. 40.0 chs. Set quarter section post. Raised mound with trench and drove charred stake.

6-3-1902 Charles Armstrong, County Surveyor (Pg.54B) found an old stake as the corner. He measured north to north section corner 1-2 and south to section corner 1-2-11-12.

12-9-1974 County Surveyor dug for this corner and found nothing.

5-21-1975 County Surveyor set a CIM over a 3/4" rod on the section line and at prorated C. Armstrong measure.

10-26-1977 County Surveyor found the CIM set in 1975, but the hugh power pole taken as an RP had been removed. Set the CIM and rod deeper to be beneath the plow line and took a transit tie to the corner.

7-2-2001 County Surveyor found CIM in good condition and located its position with GPS.

4-13-2011 Mike Hendrickson, MNDOT, found cast iron monument down 0.5'. Left monument as found. Measured the following reference ties:
Benchmark disk 5508 D in box culvert headwall - 988.25' Southwest
SE end rail of bridge no. 3505 - 1372.35 Northeast

8-15-2011 Jeff Harcey, MNDOT Crew Chief, found CIM in good condition. Set additional ties as follows: 1/2" rebar, down 0.5', Az=0 degrees 0 minutes, 50.16'
1/2" rebar, down 0.5', Az=270 degrees 0 minutes, 50.14'