Certificate of Location of Government Corner

ID#: 850107 **Description:** N SEC COR 1 2 85 **Date Set:** 10/13/09 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The CIC on Telspar Pipe is down 0.4'
The corner falls in centerline of E-W twp road and 105' west of pasture driveway south
Center of large Cottonwood SSE 100'
County Survey Disk in W side PP S 30.55'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Cushing, Deputy Surveyor; North between sections 1 & 2. 80.00 CHS. Intersected standard parallel No.2 11 chs. 15 links east of quarter section post of section 35, Twp 109N R15 west of the 5th Meridian and set post to sections 1 & 2. Erected mound with trench and pit and drove charred stake.

6-1902 Charles Armstrong (P54B) County Surveyor states corner gone. Relocated corner on range line and at 1/3 distance from N 1/4 corner section 2 to NE corner section 1. Set boulder 14"x16"x24".

1919 McGhie & Betts indicates stone found 1 1/2' deep in N ditch of old road.

6-1969 John Kerr, County Surveyor, couldn't find corner. Set CIM on line from N 1/4 corner section 2 to NE corner section 1 and at prorated Gov't measure.

5-16-1975 Roger Brand, County Surveyor found Armstrong's boulder with six notches cut in side 5.75' east and 3.9' north of Kerr's CIM. Set 10" CIM over Armstrong's stone and junk around stone. Removed John Kerr's CIM.

6-29-2001 County survey crew found CIM in good condition.

10-13-2009 Joel Thoreson, County Surveyor computed a new corner location on the standard parallel by intersecting the east line of section line 2-108-15 with the south line of section 35-109-15. County survey crew set a cast iron cap on telspar pipe at the new corner location which is 1.62' south of the existing CIM. Removed the existing CIM.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found CIC on Telspar pipe in good condition.