Certificate of Location of Government Corner

ID#: 850206 **Description:** 1/4 SEC COR 2 3 85 **Date Set:** 5/21/75 **County:** Olmsted

Section: 02 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 8 1/2' north of E-W fence
County Survey Disk in 10" Elm NE 101.2'
Steel fence post up 30" and 3' north of E-W fence ESE 15.3'
Spike in N side blazed 30" Elm W 57.15'
Post w/sign 1 1/2' South
This corner is located by GPS reference stations "Velvet B & C"

Corner History:

1854 Gov't Notes: Cushing, Deputy Surveyor; North between sections 2 & 3 25.60 chs. A river 65 links wide course SE. 40.0 chs. Set a quarter post RPs- 6" elm S39°E 12 links, 16" elm N81°W 70 links. 80.32 chs. Intersected standard parallel No.2 11.14 chs. East of the quarter post on the south line of section 35 T109N R15W.

5-21-1975 County Surveyor set CIM over a 3/4"x12" rod by gov't proportinate measure and on the section line. Note: After locating the corner by lost methods, the location fell in an area subject to high water of the river. We didn't have much chance of finding the original corner. The fences running east and west are crooked and not reliable. In this case the lost position was chosen as the best place for the 1/4 corner.

12-31-1980 County Surveyor set a survey marker, sign, and post 1.5 south of corner.

7-6-2001 County Surveyor found CIM in good condition.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found CIM in good condition.