Certificate of Location of Government Corner

ID#: 850207 **Description:** N SEC COR 2 3 85 **Date Set:** 7/10/2009 **County:** Olmsted

Section: 02 **Township:** 108N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is at the surface
The corner falls in centerline of E-W twp road
County Survey Disk in NE side TCM box brace post SE 40.08'
County Survey Disk in E side PP SW 52.64'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, John Cushing, Deputy Surveyor; North between sections 2 & 3. 80.32 chs. Intersected standard parallel No.2 11 chs. 14 links east of quarter post on south line of sections 34 in T109N, R15 west of 5th Meridian and set post for corner to sections 2 & 3. Raised mound with trench and drove charred stake.

5-19-1975 Olmsted County Surveyor found Original Gov't wood stake 3 1/2' deep in the center line of east-west twp road running 1'± into clean clay.

5-20-1975 Olmsted County Surveyor set CIM over 1 1/2"x30" pipe over stake remains.

12-30-1980 Olmsted County Surveyor found CIM but reference points taken in 1975 now gone.

11-25-1981 Olmsted County Surveyor removed CIM and pipe beneath set in 1975 and reset CIM over a 1/2"x19" rerod. 1.41' south and 0.02' east to be on the line from south section corner 34-35 to the south 1/4 corner 34 109-15 (and southerly of stake found). The monument is in the center of the E-W road. Nothing else to tie to. (Correction of corner location).

Note: CIM is set at Gov't measure 735.24' east of south 1/4 corner 34, 109-15. (Correction of corner location)

7-6-2001 Olmsted County Surveyor found CIM in good condition.

3-24-2006 Olmsted County Surveyor found CIM in good condition down 1.5', took local ties and covered CIM with blacktop.

3-27-2006 Olmsted County Surveyor set 1" pipe w/cap at surface from local ties taken from CIM. CSD w/concrete nail in NE side of TCM box brace post SE 40.15' and CSD w/concrete nail in east side of PP no # SW 52.78'.

7-10-2009 Olmsted County survey crew did not find 1" square pipe w/cap, destroyed due to underground sewer pipe construction. Reset 1" square pipe w/cap RLS #42638 using previously measured coordinates.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found 1" sq. pipe with cap RLS #42638 in good condition.

3-15-2012 Olmsted County survey crew found 1" square pipe with cap in good condition.