Certificate of Location of Government Corner

ID#: 850208 **Description:** N 1/4 SEC COR 2 85 **Date Set:** 1/13/2006 **County:** Olmsted

Section: 02 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.3'
The corner falls 5 1/2' north of centerline of E-W twp road and 2' east of fence south
County Survey Disk in E side PP SSW 38.87'
This corner is located by GPS measurement

Corner History:

6-1902 Charles Armstrong; (Pg54B), County Surveyor found limestone in road.

7-25-1969 John Kerr, County Surveyor found stake. Set CIM over 1/2"x3' rod in place of stake.

5-16-1975 Olmsted County Surveyor, after finding North section corner 1-2 dug with backhoe and found only pieces of limestone in fill. Stone possibly broken and displaced during road grading.

5-20-1975 Olmsted County Surveyor set CIM over 5/8"x12" rod as corner midway between north section corner 2-3 and north section corner 1-2 and on line between south section corner 34-35 (109-15) and north section corner 1-2. Corner is 10.4' east and 5.0' north of Kerr's CIM (removed) and 5.6' east and .25' north of location of limestone pieces.

NOTE: This is a correction of a corner, corner is 10.4' east 5.0' north of Kerr's CIM. (removed)

7-6-2001 Olmsted County Surveyor found CIM with head broken off.

1-13-2006 Olmsted County survey crew found CIM down 0.8' with head broken off but otherwise in good condition. Took local ties and removed. Found 5/8" rod down 2.2' that matched CIM ties. Set 5.0' telspar pipe with CIC down 0.5' at CIM location.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found CIC on Telspar pipe in good condition.

3-15-2012 Olmsted County survey crew found cast iron cap in good condition.