Certificate of Location of Government Corner

ID#: 850304 **Description:** 1/4 SEC COR 3 10 85 **Date Set:** 7/16/2007 **County:** Olmsted

Section: 03 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.4'
The corner falls in line with centerline of twp road south, 7' S of centerline of twp road west and in line with fence east
County Survey Disk in SW side PP SE 37.76'
County Survey Disk in N side CP E 27.67'
This corner is located by GPS measurement

Corner History:

6-12-1854 Gov't Notes: John Cushing, west on true line between 3 and 10. 39.90 set 1/4 sec post var 9° 32' E. Blk Oak 10 in S 35 E 203 lks, made trench 79.80 sec corner.

1-1861 Samuel McDowell (P.65 No.92) shows 1/4 post measured north 79-2/3 rods to 1/16 cor. He was surveying the west seven acres of the SW 1/4 of the SE 1/4 sec 3.

1978 See Dwg 4-26 Roger Brand gave McGhie's computed position.

3-18-1993 V. Fangman set temp pipe in centerline road south and in line with fence east does not fall at Roger's computed location.

7-2-2001 County Surveyor found 1/2" pipe w/cap in good condition and measured its location with GPS.

7-16-2007 County Surveyor accepted Vince Fangman's position as the corner location. Found 5/8" pipe without cap down 0.1' in good condition. Removed pipe and set 5' telspar pipe w/cast iron cap down 0.4'.

3-15-2012 County survey crew found cast iron cap in good condition.