Certificate of Location of Government Corner

ID#: 850404 **Description:** 1/4 SEC COR 4 9 85 **Date Set:** 9/30/85 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 4' south of centerline of E-W twp road and 3' east of fence line north
County Survey Disk in brace post NNW 32.96'
This corner is located by GPS measurement

Corner History:

6-12-1854 Gov't Notes: Cushing Dept. Surv., west on true line between 4-9 40.00 set quarter post in raised mound with trench and pits. 80.00 section corner.

1966 County Surveyor measured from S 1/4 5, did not find corner.

9-16-18-1985 County Surveyor dug from t.n. (set in line fence north and approx 1' S centerline in 1979) for 4-1/2' east, 4' south, 1-1/2' north and 10-1/2' west by 2-1/2' deep at east end of hole and 2' deep at west end. Digging N-S today tol cover the middle of the road and 1320 from the 1/16 N (meas 1317.87 from nail at 1/4 4-9 to nail at 1/16 N) Digging E-W to cover fence north and midway (came 7.6 W of t.n.) conditions only fair with black dirt looking a little mixed up and full of small boulders which make digging with backhoe difficult. Quick change from black to clay to sand, but could be natural here. Continued digging hole as follows. Found a small square boulder 7"x7"x11" standing with wood piece lying beside. Removed stone and found that someone had dug under it. As we dug east and south we found 4 more boulders and a limestone, but none were standing and someone had dug where they lay. Stones in an area about 1-1/2' N-S by 2-1/2' E-W. Small square boulder 4' south of centerline E-W road stone 32' ± from north road fence. There is so much shoulder on S side of road it looks like center of road could have been farther south than it is now. Square boulder is also in line with main line of fence running north (200'±) but is 3' E of fence at road (fence at road may have moved west because of boulder pile where fe line from north would come).

9-30-1985 County Surveyor set CIM over a re-rod at location square boulder stood. RP: CSD in brace post NNW 32.96

2-27-2001 County Surveyor found CIM down 0.6' in good condition.