Certificate of Location of Government Corner

ID#: 850406 **Description:** 1/4 SEC COR 4 5 85 **Date Set:** 10/3/85 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of N-S fence
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

6-12-1854 Gov't Notes: Cushing, Dept. Surveyor, north on true line between section 4 and 5. 40.00 set quarter section post. Burr oak 5 in S17W 7 lks.

11-1937 A.C. Leonard (P.471) J. Rock, a stone was set here by Mr. Page Pine Island Surveyor as avered by Mr. Arther Jewell, adjacent landowner and about 20 years ago also 5 years later a stone set at 1/16 corner south which Mr. Jewell helped set at both fences running west were built from these stones now apparently gone. Used corner posts as corners in both cases. Meas south 1329.5' to 1/16 fence west. Meas north 1106.9' to iron rod then 1618.6' to NE cor 5. Meas west 1686.8' to iron rod then 943.4' to center section 5 also iron rod 656.4' east of center 5 for line S. On line north from iron rod at 943.4' east of N 1/4 5 which was not found but relocated.

1966 J. Kerr found iron rod on Twp line 943.4' east of NW 1/4 5 which was not found.

9-20-1985 County Surveyor dug from steel fence post traverse point for 6' north, 2' west, and 2-1/2' east. Steel fence post 1/2' west of the N-S fence hole 2-1/2' deep on the west side of fence and 1-1/2 deep on east side. Found square post mark centered 4.1' north of the steel post. Line and prorated measure from center 5 over Leonard iron came 3.62' north and .83' east of steel fence post S accepted this mark as corner post used by Leonard. There was also a small post appx 1' west and not deep with 1956 can lid by it. Line and prorated gov't measure here 2.1'±N and .9'± E of steel fence post shot.

10-1-1985 County Surveyor dug a little by fence corner and dipped for iron but found only an old post stub which we shot. After finding Leonard prop cor 1679.8' west, dug east of post stub and found rust hole from iron in cultivated field appx 1.2' N and 8.15' E of post stub shot. Set spike in rust hole (down 12" +). Found 5/8"x4' re-rod by stub of post. Iron slightly bent. Straightened and put back in hole and shot.

10-3-1985 County Surveyor accepted post mark found as corner location (used by Leonard, verified by line and measure west and north). Drove long telspar with CIC at post location. Corner 4.1' north of traverse point and .8' west of the N-S fence. Drove sign and post .75' east.

3-26-2001 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.