Certificate of Location of Government Corner

ID#: 850604 **Description:** 1/4 SEC COR 6 7 85 **Date Set:** 1/25/2006 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in W side 8" Birch NNE 10.97'
County Survey Disk in N side 24" Maple W 31.88'
Post w/sign 2' SW
This corner is located by GPS reference stations "Run Off A & B"

Corner History:

9-1854 Gov't Notes: John M. Cushing, Deputy Surveyor; East on true line course between sections 6 & 7. 39.60 chs. Set 1/4 section post from which an 15" elm bears N34°W 13 links and 24" elm bears S9°E 37 links. 79.60 chs. Section corner.

9-1882 Thomas Hunter, County Surveyor, (Bk.A Pg.379 No.370 and Old Fieldbook 5 Pg.144) 1/4" post missing, but found the NW witness tree standing from which we found the stump of the SE BT and from these we reset the 1/4 post from U.S. Field notes. He used this corner to set the 1/16 west, a stake on line and at proportionate Gov't measure to the SW corner 6 and to set the center 6 a stake at intersecting 1/4 lines.

5-1900 Robert Fraser, Deputy County Surveyor, (Bk.A Pg.672 No.597 and Olf Fieldbook 15, Pg.53-56) found witness tree with marks plain. NW witness tree and running out course and distance found stub of old stake. The top had been broken off. Drove new stake. Drove iron stake beside of wooden stake. This stake is just on the east side of another tree.

11-2-1971 County Surveyor found an iron rod on the NE side of a hugh tree. Set a 1/2" pipe 5.5' long on the north side of the iron and up 12" Also set a piece of old cast iron house radiator on the east side of the rod.

3-26-1981 County Surveyor drove a telspar pipe with a CIC over the 1/2" pipe standing on the NE side of huge tree.

6-15-2005 County Surveyor found CIC on telspar pipe up 2.0', very loose but straight . Sign & post still there but huge tree & most of the fences gone. Did not try to locate 40d nails.

1-24-2006 County Surveyor found monument up 1.5' loose, removed. Found 1/2" pipe up 1.2' inside of telspar, took local ties and removed. Found radiator on east side of pipe, removed. Found iron rod lying flat on ground. Set 1/2" iron rod with plastic cap RLS #15809 at location of 1/2" iron pipe, turned angle to pipe to determine final location.

1-25-2006 County Surveyor set 6 1/2' telspar pipe w/CIC over 1/2" iron rod with plastic cap up 0.6'. CSD with concrete nail in west side of 8" Birch NNE 10.97' & CSD with concrete nail in north side of 24" Maple west 31.88'. Set post with sign 2.0' SW.