Certificate of Location of Government Corner

ID#: 850607 **Description:** NW SEC COR 6 85 **Date Set:** 7/15/65 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 95' west of N-S fence and 18' south of E-W fence
40D nail & hub in twin Elms W 79.9'
This corner is located by GPS reference stations "Becks A & B"

Corner History:

1875 State law required monuments to be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required although there is no survey notes documenting this particular corner.

9-1882 T. Hunter Pg.379 No.370; Corner gone, also 1/4 corner S36 109-16 and section corner of S36 and S31 east. Ran line NE 1/2 over N 1/4 6 and set at 80.06 ch.

5-1900 R. Fraser Pg.672 No. 597; Found square stone monument. Mr. J.Brandly avers it is properly set corner.

6-1901 W. Fraser Pg.6B; Found township corner monument. 16 east set stone and stake .

6-1929 J. Kerr Pg.424 B; Found township monument in place.

7-1965 J. Kerr set CIM down 12" in field with 3/4"X18" rod below and remaining part of original monument.

1989 Roger Brand Research of Dodge CO. Records. Found a Casper Maxson 1945 record (marked stone found). Ties: Slippery elm SW in stone pile 118', Twin elm NW 80.2', Maxson also surveyed for corners on county line going south for two miles, but no ties were given in this 1945 work.

9-19-2005 County Surveyor found CIM down 0.7' in good condition.