# Certificate of Location of Government Corner

**ID#:** 850704 **Description:** 1/4 SEC COR 7 18 85 **Date Set:** 9/16/2005 **County:** Olmsted

**Section:** 07 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 1/2' north of E-W fence
County Survey Disk in N side 12" Elm up 0.4' SE 14.62'
County Survey Disk in W side 10" Elm up 0.5' N 44.51'
Post w/sign 2' south
This corner is located by GPS reference stations "D. Miller A & B"

**Corner History:**

1854 Gov't Notes: Cushing, Deputy Surveyor; East on true line between Section 7 & 18. 39.20 set quarter section post. RPs- 5" burr oak S30E 73 links. Dug trench. 79.20 section corner.

7-1893 W Fraser Pg.524 No.489. Corner couldn't be found. Set stone 3x8x24 on line and 40.04 from SE corner South 7. 16 west set stone 5x5x25 on line with stake at 20.02 then 19.22 to SW 7. Also set 1/64 stake M & L 10.01 S 1/4 7 & 1/16 west.

11-3-1971 County Surveyor measured from center road 19.75 ± N of CIM at 7-8-17-18 west 20' north of E-W fence. Found limestone 3x8x17 at 2642 ±. Set bottom part of steel fence post on north side of stone. Set point 8 north for random line west. Set nail at 1320.75 on random line 1321.32.

11-9-1971 County Surveyor found 18" of 5x5x25 L stone at 1/16 corner. Set 1"x4' thin iron pipe on west side of stone with glass and multi colored stone on east side of stone.

9-16-2005 County Surveyor found stone down 0.3' in good condition with steel post directly south, took local ties to stone and removed. Set 5' telspar w/CIC up 0.5' from ties, removed steel post and placed stone flat on north side of monument. Set sign and post 2' south. Updated all ties.