Certificate of Location of Government Corner

ID#: 850705 **Description:** W SEC COR 7 18 85 **Date Set:** 8/7/1989 **County:** Olmsted

Section: 07 **Township:** 108N **Range:** 15W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls 0.8' west of centerline of CSAH 5
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor; North between sections 13 & 18. 80.0 chs. Set section post. RPs-5" burr oak N17°E 89 links, 4" black oak S28°E 57 links. Built mound and pit 8 links south.

7-1893 William Fraser (Pg.524 No.489), County Surveyor found 3 boulder stones with 2 stakes driven between and an old horseshoe beside one stake. Set a 5"x5"x25" stone with a stake at the 1/16 east.

2-1892 Thomas Fraser (Pg.471 No.452), County Surveyor couldn't find corner.

11-1-1971 County Surveyor found the 1/4 corner 7-18 and the 1/16 west. Set a 3/4"x10" rod on line from 1/4 corner 7-18 over the 1/16 west and at prorated Will Fraser measure.

9-7-1976 County Surveyor found 3 boulders with a stake between them 5 1/2' deep .01' south and .82' east of the rod set in 1971. Set a 1 1/4" pipe on the south side of the stake. Set a CIM over a 3/4"x10" rod over all.

7-16-1985 County Surveyor took transit tie.

8-7-1989 county highway department set 5/8" brass plug 0.8' west of centerline CR #5 20' north to centerline of field drive.

3-22-2005 County Surveyor found brass plug in good condition at surface. Field drive to the south abandoned/gone.

10-23-2006 County Surveyor found 5/8" brass plug at surface in good condition.