Certificate of Location of Government Corner

ID#: 850904 **Description:** 1/4 SEC COR 9 16 85 **Date Set:** 10/23/75 **County:** Olmsted

Section: 09 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in open field 123' east of N-S fence
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes; John Cushing, Deputy Surveyor, West on true line between section 9 & 16. 40.0 chs. Set quarter section post. 6" aspen S28E 3 links, 4" cherry N78°W 38 links.

12-1894 William Fraser (Pg.556 No.513), County Surveyor found stake remains. Drove new stake. Tested corner by running line and measure from NW corner section 16 over boulder found at 1\16 corner east of NW corner section 16 and found correct. Also measured east to ne corner section 16.

9-1964 John Kerr (Bk.89 Pg.63), County Surveyor didn't find corner. Corner came in cultivated field. Located corner E-W by measuring east from the fence north at the 1/16 east of NW corner section 16 (1/16 corner under pipe of boulders at fence corner).

10-5-1971 County Surveyor measured south line of section 9. Corner comes in open field.

10-23-1975 County Surveyor set CIM (deep) over 1/2"x18" rod in open field at William Fraser's prorated measure after digging 3'x4' to clean clay and finding nothing.

3-27-2001 County Surveyor found CIM down 0.9' in good condition.