Certificate of Location of Government Corner

ID#: 851004 **Description:** 1/4 SEC COR 10 15 85 **Date Set:** 10/5/71 **County:** Olmsted

Section: 10 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 6 1/2' south of centerline of twp road west and 13' west of centerline of N-S twp road
Punch mark in N end 24" CMP NW 43.5'
Punch mark in S end 24" CMP SW 36.5'
Punch mark in telephone cable box SE 51.2'
Bottle cap in N side PP #23765 E 38.25'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes-Cushing, Deputy Surveyor; West on true line between 15 & 22. 39.985 set quarter section post. Made trench. RPs-16" burr oak S87W 295 links. 79.97 section corner.

12-1894 W Fraser Pg.556 No.513; Couldn't find nothing or any evidence of corner or bearing trees.
Run section line and set boulder stone M & L at 39.25 5/6. 16 east set iron, 16 south drove stake M & L, 16 center NE 1/4 drove stake and set boulder at true intersecting lines.

10-4-1971 County Surveyor found rust hole where iron stake. Where corner was set by W.Fraser 12-1894. Found triangular shaped boulder 16" down 2.5'. Set 5/8"x18" rod under stone with CIM over both.

9-16-1981 County Surveyor, 1/16 south found 1/2" pipe. Dug north and south to cover any corner by Will Fraser and found nothing, set pipe back.

7-25-2001 County Surveyor found CIM down 0.7' in good condition.

12-10-2002 County Surveyor found CIM down 0.7' in good condition.