Certificate of Location of Government Corner

ID#: 851006 **Description:** 1/4 SEC COR 9 10 85 **Date Set:** 1/27/2006 **County:** Olmsted

Section: 10 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6 1/2' west of centerline twp road north and 6' north of centerline twp road east
The monument is down 0.5'
Bottle cap in NE side PP SE 49.03'
County Survey Disk in E side TCM box brace post SW 60.99'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes Cushing, Deputy Surveyor; North between sections 9 & 10. 40.0 set quarter section post. RP- 8" black oak N52E 25 links and made trench.

12-1894 W. Fraser Pg.556 No.513; Found no knowledge or evidence of corner. Set iron stake M & L 40.11'. 16 north drove iron stake M & L.

10-6-1971 County Surveyor set CIM over iron and original L stone.

2-16-2001 County Survey Crew found CIM with head broken off down 0.7' in good condition.

1-27-2006 County Survey Crew found CIM with head broken down 0.7', took local ties and removed. Found 5/8" iron rod down 2.7', ties matched, removed. Set 4' telspar pipe w/CIC down 0.5' from ties taken from CIM. Bottle cap in NE side of PP no # SE 49.03' and CSD with concrete nail in east side of TCM box brace post SW 60.99'. Did not try to locate stone.

5-10-2010 County Survey Crew found CIC/p2 down 0.5' in good condition.