Certificate of Location of Government Corner

ID#: 851304 **Description:** 1/4 SEC COR 12 24 85 **Date Set:** 10/31/85 **County:** Olmsted

Section: 13 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 16' east of centerline of N-S driveway and 20' north of centerline of E-W driveway
This corner is located by GPS measurement

Corner History:

6-12-1854 Gov't Notes: Cushing, Dep. Surveyor, west on true line between sections 13 and 24. 40.00 set quarter section corner. Raised mound, dug trench, and drove charred stake as instructed. 80.00 section corner.

1-1892 Thos Fraser (P.468 No.450) corner gone. Nothing could be found of it. Mr. D. Van Horn avers stake stood on west side of old track. Line run M&L 39.80 2626.8' brought corner at that spot. No desc of corner set only method imployed in setting.

4-1871 R. Perry (P.181 No.192) found stake in mound, no meas etc

4-1903 CA Armstrong (P.49B) survey only plat, no desc. S 1/4 13 shows as post. 16 north stake M&L 19.90. 16 west stake shown M&L 19.94 to fence corner. 16 east stake shown M&L 19.94 to stone old BT's.

10-1985 County Surveyor dug as follows (see card) dug M&L for corners set by Thomas Fraser and C. Armstrong but could not find stakes. Dug along W edge old road for original corner as remembered by Mr. Van Horn in T.F. survey No.450 P.468. Dug across road in line with fence running east to cover line projected from the S 1/4 24 over the fe N at the center 24 which came 18' east of midway. Found remains of a small post 17.06 17' E and 5.41 5-1/2' N of M&L. Post had been dug around. Drove 1x2 hub to hold location. Also found 60d spike driven in old road 3.97 N and 10.54 E of M&L (using Kerr SW 13).

10-30-1985 County Surveyor dug on line from N 1/4 cor 13 over the center 13 and at C. Armstrongs measure from center 13. Found stake in NE side 12"x18"x23" long boulder 2-1/2' deep in road. Top center of boulder .3 W and .3 S of stake. Stake 6.39 S and 4.98 west of t.n. set in centerline road and in line fe E. Set nail only at road survface over stake

10-31-1985 County Surveyor set 5' telspar with cast iron cap or the corner. Drove survey marker sign and post 1.0 south corner set N-S at double the measure from the iron at the center 13 (set 1977 where stake found) the N-S location of the stake found (by stone) at the 1/16 south of the center 13 and set on line from the N 1/4 cor 13 over the iron at the center 13 said line comes .26 E of the stake found at the 1/16 south of the center 13. Corner comes 2-1/2' south of the fence running east a 9' west of the center of the old road (3' from the W edge of road). corner 2.99 N and 2.17 E of M&L using Kerr's SW 13. RP's: Spike and CSD in SW side of 11" Burr Oak SE 38.07.

9-6-2005 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition. Took off cap and drove pipe down 0.3'. cast iron cap on telspar pipe now down 0.5'. Corner falls on inside edge of curve on a private driveway. 20' north of E-W driveway and 16' east of N-S driveway. Old reference ties gone.