Certificate of Location of Government Corner

ID#: 851506 **Description:** 1/4 SEC COR 15 16 85 **Date Set:** 9/21/81 **County:** Olmsted

Section: 15 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of N-S fence
County Survey Disk in E side Hackberry S 55.14'
County Survey Disk in E side 13" Black Oak SW 29.76'
Sign on RR tie CP 2' WSW
This corner is located by GPS reference stations "Boyum A & B"

Corner History:

1854 Gov't Notes: John Cushing, Deputy Surveyor, North between sections 15 & 16; 40.0 chs. Set 1/4 section post from which a 4" jack oak B. S48 °E 78 links. Made trench. 80.0 chs. Section corner.

1-1858 Thomas Hunter, County Surveyor, (Bk.A Pg.48 No.70) used 1/4 post to set the 1/16 East midway (20.29 chs.)and on line to the center 15 and the 1/16 east of the center 15 midway (20.05 chs.) and on line to 1/4 corner 14-15.

12-1894 William Fraser, County Surveyor, (Bk.A Pg.556 No.513) Found stake and drove new stake with stone by its side. Used this corner to set sec. Cor 9-10-15-16 and the center of section 15, a stake and boulder along side.

3-21-1901 William Fraser(addition to survey No.513)at the 1/16 east found stake.

7-1950 John Kerr took measurements.

8-27-1981 County Surveyor dug around boulder, but didn't find Fraser's stake mark.

9-14-1981 County Surveyor found remains of old post with stake mark down 3'. Stake is 1.2' north and .3' west of the stone dug around.

9-21-1981 County Surveyor set telspar pipe w/cast iron cap at location of the stake mark found.

3-5-2001 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.