Certificate of Location of Government Corner

ID#: 851705 **Description:** SEC COR 17 18 19 20 85 **Date Set:** 10/25/71 **County:** Olmsted

Section: 17 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of N-S twp road, 2' north of centerline of twp road west and 4' north of centerline of twp road east
Punched cross in NE side of cemetery CP NW 46.45'
Concrete nail in SE side PP SW 58.50'
Plastic disc in PP NW 39.46'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: 80.0 set corner to section 17-18-19-20. Built mound with trench,and charred stake. Oak, apple, cherry, plum, and aspen in the area.

9-1856 Thomas Hunter Pg.16 No.26; 1/16 west 20.03 chs. M & L, B.T.s(S61 1/2°E 9 links)(S50 1/2°W 1 1/2 links 1/16 east 19.95 chs M & L to 1/4 post.

12-1873 T. Hunter Pg.235 No.237; Found part of stake in mound. Drove stake 2' long with flush.

3-1892 Thomas Fraser Pg.471 No.452; Corner gone, no evidence. Used Hunter's old records and set at 39.89' 2/3 from stone at 1/4 17-20. Measured SE 19 north to 1/4 17-18 (2632.4). Set iron stake as corner. RP- 14" jack oak N50 1/4 E 63 links. 16 north drove iron stake, RP-8" elm N76° E 66 1/2 links. 16 west set stake, RP- 12" jack oak S 44 1/2E 47 1/2 links.

1939 county highway department Bk.100 Pg.2; Found stone monument, but no iron mentioned. RPs- pp NW 39.95', brace pp SW 58.59', NE corner Kennedy tombstone footing NW 65.5', spike in top corner fence post SW 40.3', spike in top telephone pole SE 59.7', spike in top telephone pole NE 39.2'.

1951-52 county highway department Bk.191 Pg.3; Corner used as PI. Measured south 1/4 corner or PI 2635.72 (Bk.100 survey 2633.8). RPs- Disc in pp NW 39.95', disc in brace pole SW 58.57'. Measured north 5273.75' to section corner 7-8-17-18 SE picket fence corner cemetary. RPs-disc in pp NW 39.95', disc in pp SW 58.57'.

12-4-1969 County Surveyor, no discs in any pps. PP NW has disc on south side.

10-25-1971 County Surveyor found iron shaft(set by Thomas Fraser) and large L stone 4x10x20. Took measurements north, south, and east. Set CIM at point set.

3-23-2005 County Surveyor found CIM down 1.2' in good condition.