Certificate of Location of Government Corner

ID#: 851904 **Description:** 1/4 SEC COR 19 30 85 **Date Set:** 7/15/2013 **County:** Olmsted

Section: 19 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 1'
The corner falls in line with fences north and east and in field waterway
This corner is located by GPS reference stations "Welch A & B"

Corner History:

6-12-1854 Gov't Notes: Cushing, Dept. Surveyor, east on true line between 19 and 30. 38.50 set quarter section post. Aspen 6 in. N31E 33 lks. Aspen 5 in. ?66W 11 lks. 78.50 section corner.

11-6-1874 T. Hunter (P.264 No.262) after careful search from stump of SW BT found remains of old stake. Set new stake and took 2 witness trees. 10" Br Oak S65-1/2°E 57 lks 37.62'. 12" Br. Oak S7°W 69 lks 45.54. 16 east set stake M&L 19.96 1317.36'. Meas south to center 30 a stone 4x5x12 and stake, set at true inters lines 39.71 2620.86.

5-23-1910 Ch. Larson (P.124B) this survey confusing as to way drawn and described. Accepting top of drwaing as east (not north) corners and measurements make good sense otherwise not. 1/4 19-30 not used but evidently aerial of E-W 1/16 of N 1/2 30 run and point set 38.27 2525.82 east of iron set as 1/16 M&L 19.82 1308.12'. W. Fraser got 1306.65' between same corners, gov't meas west 1/2 30 N 3850. Hunters E 1/2 2634.72 so 38.27 could be acceptable as mean. P.124B corner as "4" written as 1/4 cor could not be center 30 as north 1/2 mile "3" written as sec corner. 1/4 corner limestone with 1/16 north 19.89 1312.74 an iron stake.

10-20-1971 County Surveyor walked to corner area and found entire area dozed with power machinery. Trees in massive pile.

6-7-2004 County Surveyor visited area of corner. The area falls in middle of a waterway.

7-15-2013 County survey crew set a 4' telspar pipe with cast iron cap in line with fences north and east.