Certificate of Location of Government Corner

ID#: 851905 **Description:** W SEC COR 19 30 85 **Date Set:** 8/7/89 **County:** Olmsted

Section: 19 **Township:** 108N **Range:** 15W **Monument Description:** 5/8" Brass Plug

Reference Ties:

The corner falls 0.2' east of centerline of CSAH 5 and 3' north of fence west
SW corner house foundation NW 120.83'
NE corner house foundation NW 117.01'
County highway disk in PP #23225 NW 50.98'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; North between sections 25 7 30. 80,0 chs. Marked aspen 4" in diameter for section corner. RPs-16" black oak S25°W 45 links,8" aspen N30°W 10 links, 8" aspen N8°E 15 links, 8" aspen S40°E 18 links.

8-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old Road Book--Road No. 66) surveyed a road on the west line of sections 19 and 30.

2&3-1892 Thomas Fraser, County Surveyor, (Bk.A Pg.471 No.452 and Old Field Book 8 Pg.11) couldn't find this corner.

1-1896 William Fraser, County Surveyor, (Bk.A Pg. 589 No.535) located and drove iron stake on line and at 1/4 the distance from the west 1/4 corner 30 to the w 1/4 corner 18. Set an iron stake at the 1/16 south, 1/16 north, west 1/4 corner 19, at 1/16 north of the west 1/4 corner 19, and west section corner 18-19.

5-28-1980 This corner comes in a deep cut in CR #5. County Surveyor set a 1/2"x18" rod on line from the west 1/4 corner 30 (found) to the west section corner 18-19 (found Fraser's iron) and at prorated Will Fraser measure as per Survey #535. We found Fraser's irons at the 1/16 north, west 1/4 corner 19, 1/16 north of the west 1/4 corner 19,and west 18-19 and also the stone at the west 1/4 Corner 30. We found Fraser's line and measure to be very accurate on this 1 1/2 miles.

7-16-1985 County Surveyor, corner may be destroyed by road construction. Set 5/8" rerod .8 south of fence running west (down 1'). 5/8" rod .7 west of eyeball of east side of house to north.

8-7-1989 county highway department set 5/8" brass plug in centerline CR #5. RPs- CSD in 3' stump west 69.95', county highway department disc in pp NW 50.98'.

6-1-2004 County Surveyor found 5/8" brass plug with punch mark at surface in good condition.

10-23-2006 County Surveyor found 5/8" brass plug at surface in good condition.