Certificate of Location of Government Corner

ID#: 851906 **Description:** W 1/4 SEC COR 19 85 **Date Set:** 8/7/89 **County:** Olmsted

Section: 19 **Township:** 108N **Range:** 15W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls in centerline of CSAH 5 and 5 1/2' south of centerline of residential driveway west
County highway disk in PP #49801 SW 49.44'
NE corner of concrete block foundation of addition to metal shed NW 118.95'
NE corner of concrete foundation of corn crib NW 103.25' (slope)
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; North between sections 19 & 24. 40.0 chs. Set quarter section post. RPs-8" black oak N56°E 12 links, 10": black oak N51°W25 links.

9-1856 Thomas Hunter, County Surveyor, (Bk.A Pg.16 No.26 and Old Field Book 13 Og. 115) probably used this corner to set the center 19 and the 1/16 east of the center 19.

8-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (old Road Bk.--Rd.No.66) surveyed a road on the west line of section 19.

2 & 3-1892 Thomas Fraser, County Surveyor, (Bk.A Pg.471 No.452 and Old Field Book 8 Pg.11) couldn't find this corner.

1-1896 William Fraser, County Surveyor, (Bk.A Pg.589 No.585) located and drove iron stake on line and midway from the west 1/4 corner 18 to the west 1/4 corner 30. He set iron stake at the 1/16 north, at west section corner 18-19, at 1/16 south, and at west secttion corner 19-30.

1940 Dodge County HWY Dept. (Dodge county highway department Bk.22 & Bk.131) assumed corner at the centerline of twp road east.

1973 county highway department (county highway department Bk.191 Pg.2) shows a drag tooth in the centerline CR #5 for the start of a grading job east.

5-16-1980 County Surveyor dug and found a 5/8" bolt with a 1" square head 5' deep. We also found Fraser's iron at the 1/16 north, at west sec. Corner 18-19, at 1/16 south as well as the stone at the west 1/4 corner 30 and found Fraser's line and measurements very accurate on this 1 1/2 miles.

5-27-1980 County Surveyor set a 1/2"x18" rod as the corner on line from the west 1/4 corner 30(found) to west section corner 18-19 (found Fraser's iron) and at prorated Will Fraser measure as per Survey No. 535. The corner came .22 north and .04 east of the bolt location. RPs- CSD SE side pp#23235 in yard SW 86.42, NE corner (concret block foundation) of addition to metal shed NW 118.95, NE corner (concrete foundation) of corn crib NW 103.25 (Slope).

7-16-1985 County Surveyor, corner may be destroyed by road construction. Set 5/8" rerod 1.0 south of a wood fence post in fence line running east (fence 30 1/2'north of corner). Additional RPs-small nail in nly side 24" burr oak West NW 87.13, CSD in pp#23235 SW 86.36(old tie).

8-7-1989 county highway department set 5/8" brass plug in centerline CR #5. RP-county highway department disc in pp WSW 49.44'.

3-22-2005 County Surveyor found brass plug in good condition at surface. Did not check ties.

10-23-2006 County Surveyor found 5/8" brass plug at surface in good condition.