Certificate of Location of Government Corner

ID#: 852004 **Description:** 1/4 SEC COR 20 29 85 **Date Set:** 5/30/2013 **County:** Olmsted

Section: 20 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.1'
This corner is located by GPS reference stations "Mud Stuck A & B"
Post with sign 2' west
The monument falls in line with N-S fence

Corner History:

1854 Gov't Notes: Cushing, 40.00 set temp 1/4 sect post west on true line between sections 20 and 29 variance 9° 22' E. 40.00 set 1/4 section post from which an elm 18 in bears N 34 W 24 links. Burr Oak 10 in bears S 10 E 30 links.

9-19-1856 T. Hunter (Book A, P.16 No.26) shows 1/4 post meas north 39.91 chs to center sec.

2-5-1877 T. Hunter (Book A, P.306 No.301) corner gone, found NW BT standing and stump SE BT reset 1/4 post by witness tree gov't notes. Meas east 40.07 SE 20 not found. 16 west set stake M&L 20.12-1/2 1328.25 W edge wedge brook. Meas north 39.82 N 1/4°W. Meas south 40.08 S 1/4°E.

6-1-1910 Ch. Larson (Book B, P.126B) could have used corner to set 1/16 east and other points.

6-10-1985 Vince Fangman found 1/2" rod in line with fences N-S-E.

6-7-2004 County Surveyor visited area of corner. Found nothing. Fence east now gone.

10-5-2012 County survey crew found 1/2" rod in good condition

5-30-2013 County Surveyor accepted the 1/2" rod by Vince Fangman as the corner location. County survey crew found the 1/2" rod in good condition. Removed and replaced with a 4' telspar pipe with cast iron cap.