Certificate of Location of Government Corner

ID#: 852604 **Description:** 1/4 SEC COR 26 35 85 **Date Set:** 10/12/71 **County:** Olmsted

Section: 26 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of N-S twp road and 5' south of centerline of field entrance east
40D nail in SW side 18" Walnut SE 35.57'
Conc. Nail in NW corner RR tie gate post NE 30.9'
Punched cross in N end 15" CMP NE 35.55'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Cushing; 40.0 set temporary 1/4 section post west on true line between sections 26 & 35 V9° 11'E 40.0 set 1/4 section post. RPs- 12" aspen S81 W50 links, 16" white oak S58 E 109 links.

1-1862 Samuel McDowell Pg.67 No.94, Used 1/4 corner to set center section 35 & breakdown west 1/2 section 35.

2-1882 T. Hunter Pg.373 No.364; Corner gone, no knowledge. Set temporary stake M & L 40.04 1/2 (2641.65'). 1/16 south found small J oak tree with in inches of M & L 19.96 (1317.36' found stone 32 links south). 1/16 center NW 1/4 35 set marked stake M & L 20.15 (1329.9' on E-W 1/16 line. RPs- 6" jack oak S35°W 44 links, 6" jack oak N40°W 14 links.

11-1887 T. Hunter Pg.424 No.413; Corner Pg.373 missing, replaced corner by measure from east 40.02 1/2 and from the south as in pg.373. Set quarry stone 2x6x20. Set stone east on line and 1/4 of 40.02 1/2. North set stake.

1-1902 W Fraser Pg.28B; Found stone 37 links west of post on east side of road. South set stake .

10-22-1968 J. Kerr , Set 3/8"x14" on hill brake 600± west of N-S road. Also set 1/2"x18" rod on east edge traveled road on true section line. RP's- 21.25 to hard anil in RR tie gate post NE, 31.5 to center walnut tree SE.

10-12-1971 County Surveyor found rod on east edge of road. Rod on hill and in center of rod set by Perk Highum. Dug and found recorded limestone 3.11' south of corrected E-W line run by J. Kerr. Set stone north side rod so point could be found easily, walnut still in place. Set old radio, junk & 36" v shaped 2" steel bar on east side of stone centering over stone with CIM over all.

3-25-2005 Yaggy Colby Survey Crew found monument in good condition.

8-10-2005 County Surveyor found 1" pipe w/cap down 0.1' in good condition and removed. Found CIM down 1' in good condition.