Certificate of Location of Government Corner

ID#: 852605 **Description:** SEC COR 26 27 34 35 85 **Date Set:** 10/22/68 **County:** Olmsted

Section: 26 **Township:** 108N **Range:** 15W **Monument Description:** 1" iron pipe

Reference Ties:

The corner falls in N-S fence line on edge of wooded pasture
Post w/sign 2' east
This corner is located by GPS reference stations "River Farm A & B"

Corner History:

1854 Gov't Notes: Cushing; 80.0 set post for corner to sections 26-27-34-35. RPs-6" aspen S76 E34 links, 12" aspen S28 W 88 links, 10" aspen N86 W 68 links.

1-1862 S. McDowell Pg. 67 No. 94 used sec. cor. for breakdown of west 1/2 sec. 35.

2-1882 T. Hunter Pg.373 No.364; Found corner standing, tested by all identified witness trees or stumps proving corner correct. 16 South found stake standing M & L 19.88 1/2, 16 center NW 1/4 35 set marked stake M & L 20.15.

1-1902 W. Fraser Pg.28B; Found stake standing, evidently left as is. South set temporary stake 3.37 1/2. 16 south stake set in former survey, set stakes 7.25.

6-1946 J.Kerr B30 P57; Found limestone at fence corner averred as true corner. South found or set stone at fence corner south 327.63. 16 south found remains of stake Pg.373 driven to bedrock south of corner fence post. Reset with 2" stake and 6x8x10 boulder by side 10" elm NNE 5.7'.

10-22-1968 J.Kerr; Set 1"x5' pipe up 10" in place of lime stones in springy wet hillside, original stones by sides of pipe. South found stone 327.6 on east side new creosote corner post. 16 south didn't have proper equipment of find corner. Elm now over 18" in diameter, corner fence N & W 6' west and 1' south of tree indicating stone in clean open grass land south.

8-27-1993 County Surveyor found John Kerr pipe in good condition.

8-25-2005 County Surveyor found 1" pipe up 1.2' in good condition. Monument falls in N-S fence on edge of woods/pasture. Did not set any ties, set sign and post 2.0' east.