Certificate of Location of Government Corner

ID#: 852705 **Description:** SEC COR 27 28 33 34 85 **Date Set:** 1/25/2006 **County:** Olmsted

Section: 27 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in E side 4" Maple up 1.4' SSW 13.02'
County Survey Disk in NE side 12" tree up 1.7' SE 15.95'
County Survey Disk in SE side 13" tree up 5' NE 21.10'
Post w/sign 2' south
This corner is located by GPS reference stations "Thorpe I & II"

Corner History:

1854 Cushing; 80.0 set corner section to 27-28-33-34. RP- 10" elm N53 E 41 links, 8" hickory S57 W 36 links.

5-1863 P.C. Compton Pg. 70 No. 99 shows section corner.

12-1897 W. Fraser Pg.614 No.558; Found stake at corner with remains of old stake in the ground by its side. Drove new stake in place of old stake and planted stone by its side. 16 west drove drag tooth M & L, 16 south drove stake and drag tooth M & L, west of above 1/16 drove stakes on E-W 1/16 line.

7-1910 Charles Larson Pg.130 B; Found corner set in former surveys.

5-1946 county highway department B146 No.49; Run line from NW corner stone section 33 over stone at 1/4 28-33 doubling measure of 2626.6. Set 1"x2" hub. RP- 8" ash NE 17.8, 20" elm SE 22.0, 6" ironwood SW 5.0'.

12-1-1970 County Surveyor found W.Fraser corner or part of original stone and deep stake hole.

11-9-1971 County Surveyor reset 1/4 33-34 with CIM at corner described 5.3' west of CIM set 1965. J.Kerr removed old CIM. Measured new CIM to 1/16 shaft north 1306.87.

11-10-1971 County Surveyor rerun aerial from CIM as reset at 1/4 33-34. Set 4' long piece of red top type steel post at corner with limerock piled around corner up 10". Corner as set lies 3.9' north of direct line of NW 33 over 1/4 28-33 or 1/4 28-33 lies 1.95 south of direct line between section corners as set.

4-25-2000 County Surveyor found T-post up 0.3' in good condition.

1-25-2006 County Surveyor found "T" post up 0.3' in good condition, took local ties and removed. Set 5' telspar w/CIC up 0.3' from local ties taken from post. All older ties without CSD's gone. CSD w/60d nail in SE side of 13" tree up 5' NE 21.10', CSD w/60d nail in NE side 12" tree up 1.7' SE 15.95' and 60d nail w/CSD grown over in east side of 8' Maple up 1.4' SSW 13.02'. Set sign and post 2.0' south.