Certificate of Location of Government Corner

ID#: 852804 **Description:** 1/4 SEC COR 28 33 85 **Date Set:** 7/20/2004 **County:** Olmsted

Section: 28 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of centerline of E-W twp road and 1' west of fence north
Bottle cap in PP #23001 N 36.08'
Concrete nail in knot on W side TP SSE 39.7'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Cushing; 40.0 set temporary 1/4 section post west on true line between sections 28 & 33 V9°12'E. 39.90 1/2 set 1/4 section post. RPs- 10" burr oak S39W 7 links, 6" white oak N6E 9 links

5-1863 P.C. Compton Pg.70 No.99 shows 1/4 post used to set center 28 at intersecting lines.

1897 W.Fraser (BK.A Pg.614) relocated the corner midway and on line with a stake as corner and set a stone beside the stake.

1910 Charles Larson (Bk.B Pg.130) found the corner

1946 county highway department found the boulder and limestone. RP- Spike hub S 75.0, spike hub north 75.0 on transit line

12-1970 County Surveyor; Found axle shaft at 28-29-32-33. Measured east.

10-15-1971 County Surveyor dug and found 6"x8"x16" stone with stake on south side. Drove 1/2"x34" re-bar in stake hole with small riser.

7-7-1972 County Surveyor found iron. Set CIM over iron set below 10-15-1971. Set no further RPs.

7-19-2004 County Surveyor found CIM down 0.6' leaning east.

7-20-2004 County Surveyor removed CIM and found 1/2" rerod down 3' in good condition. Removed rerod and set 7' telspar pipe with cast iron cap down 0.5'.