Certificate of Location of Government Corner

ID#: 852805 **Description:** SEC COR 28 29 32 33 85 **Date Set:** 6/8/2004 **County:** Olmsted

Section: 28 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' north of centerline of E-W twp road and 4 1/2' east of centerline of CR 105
Point of heavy angle steel fence corner NE 40.61'
Bottle cap in CP SE 42.83'
Punched cross in W end 18" CMP SW 39.1'
County Survey Disk in PP #22990 NW 57.34'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes; Cushing, 80.0 set post to corner. RPs- 8" burr oak S11E 12 links, 6" aspen S11W 48 links, 4" aspen N40W 60 links

1875 T. Hunter (Bk.A Pg.269) found the stone in the center of the road. 16 west set stake, 16 center set stake.

1895 W. Fraser (Bk.A Pg.590) found the stone. 16 north set stake, and 16 west set stake.

12-1897 W. Fraser Pg.614 No.558 found stone.

1910 Charles Larson (Bk.B Pg.130) reset the corner from the SW corner of section 33 over the W 1/4 section 33. Set a 6"x12"x21" stone over a hole filled with lime.

1940 county highway department (Bk.103 Pg.59) found 2" auger hole full of lime. Set 1" axle in hole. RPs- V knotch in NE corner of first step in school entry SW 102.3', steel spring leaf in fence line SE 71.0'.

1946 county highway department (Bk.149 Pg.49) found a 3/4" iron rod over the hole filled with lime and set a large 1" axle shaft.

12-1970 County Surveyor found end of large axle shaft down 18" in center E-W roads within 23' of line fence north on east side of road; 8' east centerline road south set hub over corner. Measured east 2625.5' to line fence north. RPs- Extreme NE corner bottom step of school SW 101.5', 20D nail in pepsi cap NE side 14" corner fence post SE 42.7', point of angle corner post NE 40.72', point of angle corner post NW 50.8', pepsi cap on SW side pp#22990 NW 57.4'

11-10-1971 County Surveyor found and proved iron as corner.

7-7-1972 County Surveyor set CIM over iron 3/4"x26".

7-23-1999 County Surveyor found 5/8" pipe with plastic cap down 0.9' in good condition. Corner falls 1/2" north of centerline 85 St NW and east of centerline of CR 105.

6-1-2004 County Surveyor found 5/8" pipe with cap down 0.9' in good condition. Removed pipe and found CIM down 1.9' in good condition.

6-8-2004 County Surveyor found CIM down 1.9' in good condition. Removed CIM and found 3/4" rerod down 3.5' in good condition. Removed rerod and set 7' telspar pipe w/cast iron cap down 0.4'.