Certificate of Location of Government Corner

ID#: 852905 **Description:** SEC COR 29 30 31 32 85 **Date Set:** 10/18/71 **County:** Olmsted

Section: 29 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of E-W twp road and 1' west of centerline of N-S twp road
Spike in SE side PP #22941 SW 49.15'
Punch mark in top W end 24" CMP SW 37.03'
Small thin telephone cable marker post NNE 72.7'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Cushing; 80.0 set post for corner to sections 29-30-31-32. Made trench. RPs- 6" burr oak N10 E84 links, 10" burr oak N26 E 138 links, 10" burr oak S81 E 168 links.

11-1874 T. Hunter, Pg.264 No.262; Found stone. Tested 2 bearing trees and found corner didn't check out. Dug and found old piece of stake. Removed stone and set where stake was found. 16 west set boulder 5x8x14.

6-1910 Charles Larson Pg.128B; Found stone set in former survey.

1940 county highway department found boulder. Mr. Pierce avers boulder as true corner. RPs- Spike in pp SE 49.2, spike in 30" maple N17°E NNE 80.7, spike in 16" maple SE 104.1.

12-2-1970 County Surveyor inspected prospects of finding corner. All ties in place trees large, especially NNE one. Tree center within 18" area. Corner may be fairly deep if SE tie is level out.

10-18-1971 County Surveyor found pointed boulder 7x10x14. Placed old car radio on east side with CIM over stone.

5-7-1979 County Surveyor found CIM ok.

6-1-2004 County Surveyor found CIM down 0.9' in good condition.