Certificate of Location of Government Corner

ID#: 853004 **Description:** 1/4 SEC COR 30 31 85 **Date Set:** 6/3/2004 **County:** Olmsted

Section: 30 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 10' south of centerline of E-W twp road and 6' east of fence south
The monument is down 0.3'
Punched cross in top W end CMP NE 102.47'
1/2" pipe under fence SSW 52.75'
This corner is located by GPS measurement

Corner History:

8-1854 Gov't Notes: John Cushing, Deputy Surveyor; east on true line between sections 30 & 31. 38.19 set 1/4 section post. Raised mound with trench and drove charred stake. 78.19 chs. To section corner.

11-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy,(Old Road Bk.--Rd No.82) surveyed the road between sections 30 & 31.

11-1874 Thomas Hunter, County Surveyor (Bk.A Pg.264 No.262 and Old Filed Book 4 Pg 6-7) found stone planted in center of road said by Mr.N.V. Rowey to have been set by R.J. Perry, Surveyor, where old stake stood. Used this corner to set the center 30, a stone at a property corner 6.3 chains east and a boulder stone 14"x8"x5" midway and on line at the 1/16 east.

5-27-1980 County Surveyor dug for the corner, but found nothing.

5-28-1980 County Surveyor dug and found a 5"x8"x14" boulder at the 1/16 east as recorded by Hunter 7 1/2' deep. Set 1"X36" iron rod over the stone.

5-30-1980 County Surveyor dug at Hunter's property corner and found a 9" boulder.

6-3-1980 County Surveyor set a CIM over a 3/4"x21" thinwall pipe on the line and at double the measure from sec. Cor. 29-30-31-32 over the 1/16 west found 5-28-1980.

6-3-2004 County Survey Crew found 1/2" pipe w/cap RLS #14888 down 0.8' in good condition. Removed 1/2" pipe and found Cast Iron Monument without head down 1.7' in good condition. Removed Cast Iron Monument and found 3/4" pipe down 2.6' in good condition. Removed 3/4" pipe and set 6' telspar pipe w/cast iron cap down 0.3' and measured its position using GPS.